

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 28.11.2021		District: Muzaffarpur
Division : Muzaffarpur East - I		Length (km): 1.025
Name of the Road: MMHSY 5051 (Machhali Mathi) to Kundaaha to Ayodhya Road to K. B. K. K.		
Scheme/Programme: MMHSY (SE)		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any No rain cuts.	S
Observation Remarks:- Surface Condition is Satisfactory.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR.

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer: Arun Kumar Singh

Designation: Executive Engineer
RWD, Regional Lab. Bhagalpur.

EE, Muzaffarpur East I - Sri Bryan Bishwakar.

28.11.2021
(Signature)