

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 25.11.2021	District: Araria
Division : Farbisganj	Length (km): 1.380
Name of the Road: Baignathpur to Barahmpur	
Scheme/Programme: New MR	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:- At some stretches bushes were found in flank.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:- Painting of Head walls in Hume pipe ^{culvert} not done.

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Pramod Kumar

Designature:- EE, RWD, R. Lab Sasaram

EE, RWD, W. Divⁿ Farbisganj - Sri Arsal Prakash AE

(Signature)