

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 28.11.21	District: Araria
Division : Forbishingang	Length (km): 4.227
Name of the Road: L032 - Simaraha to Pothia Dhurmagarh	
Scheme/Programme: PMGSY	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	V
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	V

Observation Remarks:-

Edge of BT portion damage longitudinally in some stretches.
Raincut in flank seen.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S

Observation Remarks:-

Painting in parapet is not proper

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Pramod Kumar
Designation:- EE, R.I.B., Sasaram

EE, W. Div. - Forbishingang — Sri Anand Prakash

(Signature)

28.11.21
EE