## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 27,11,2021 District: - Arabib			
Division: Date:			
Name of the Road: 1051 Harris (M): 4,295			
Name of the Road: Losi - Hingary To Musulmay Toly (VRSI) Scheme/Programme: PMGSY			
2	No. Panameters to be checked	Remarks (S/U)	
1	The state of the s		
a)	Condition of Surfacing	S	
b)	Riding Quality	S	
c)	Road Camber	S	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	5	
e)	Contraction Joints provided or not (CC Pavement)	2	
f)	Compaction of flank/slope & raincuts if any	U	
Obse	Observation Remarks:- Raincut in the flance at some part		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	3	
c)	Condition of railings/slab/approach for Bridges	2	
d)	Condition of Vent Clearance	2	
Observation Remarks:-			
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	2	
Observation Remarks:-			
4.	Compliance History		
a)	Status of ATR's & any others		
Överall I	Overall Rating :		
	Satisfactory (S)/ Unsatisfactory (U)	S	
Name of Officer:- framod Kumas  Designature:- EE, R. lab Sanaram  EE, RWW, W Dev? Footsigany - Soo Amal Prakash 27/11/002/  (Signature)			