

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 28.11.21	District: Araria
Division : Forbisgang	Length (km): 6.682
Name of the Road: L051 - NH57 Ranigang to Nathpurnasatgong boarder	
Scheme/Programme: PMGSY	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	—

**Observation Remarks:-**

wearing course of BT layer damage at several places.

2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

**Observation Remarks:-**

3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

**Observation Remarks:-**

4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :


Satisfactory (S)/ Unsatisfactory (U)

U


Name of Officer:- Pramod Kumar

Designature:- EE, R. lab. Sasaram

EE, W. Div., Forbisgang - Sri Amal Prakash

  
28/11/2021  
AE

(Signature)

  
28.11.21  
EE