

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 26.11.2021		District: Arasia
Division : forbisganj		Length (km): 1.795
Name of the Road: L052- PWD To Simarban north (VR52)		
Scheme/Programme: PMGSY		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:-

Flank in PCC portion is not adequate
Raincut in some stretches.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Prasad Kr
Designation:- EE, R. Laboratory Sasaram
EE, RWD, W. Div forbisganj- Sri Anand Prakash

26/11/2021

(Signature)

26.11.21
EE