

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 26.11.2021		District: Araria
Division : Forbisganj		Length (km): 3.343
Name of the Road: Hasaipur To Adiwasi Talga		
Scheme/Programme: MMGSY (ST)		


Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Pots appears in the wearing course of ST layer in several stretches.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- Painting not done in HP culvert		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	


Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Pramoel Kumar
 Designation:- EE, R-Lab. Sonarum
 EE, RWA, W. Dev. Forbisganj. Sri Anil Prakash


 (Signature)
 26/11/2021
 AE


 26.11.21
 EE