

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 26.11.2021		District: Arasia
Division : Dohisganj		Length (km): 2.715
Name of the Road: Dummahay Path PMGSY To Goh Tola		
Scheme/Programme: MMGSY (WR)		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- Raincut in side slope in some stretches.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :


Satisfactory (S)/ Unsatisfactory (U)


S

Name of Officer:- Pramod Kumar

Designature:- EE, R.Lab. Sasaram

EE, RWA, W.D.R. Dohisganj - Sri Anand Prakash


26/11/2021
AE (Signature)


26.11.21
EE