

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 29/11/2021 District: East Champaran
 Division : Chakia Length (km): 2.96
 Name of the Road: NH-28 to Balochan via Bermadia Road
 Scheme/Programme: New M/R

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	N-A
e)	Contraction Joints provided or not (CC Pavement)	N-A
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N-A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N-A
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating *Satisfactory*

(Ramkishan Prasad)
 29/11/21

Bindu Rajan
 29/11/21
 Ex-Engineer
 Reg. Lab. D. Chhangan