

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 28.11.21

Division: Tikari

Name of the Road: Const of Road from village Savada PMHSY road via Vinay Nagar Mahadevi talga to Ambamathurapur Gaya SH101

District: Gaya

Length (km): 2.70 K.M

Scheme/Programme: NABARD (maintenance)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- (Approx) from ch. 0 to 2.2 - B.T. - some patch filled but not fully. " 2.2 to 2.4 - pcc - exposed aggregate, are seen. " Branch road - B.T - few patches existing, needs repair. Compaction of flank/slope is not maintained.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Sign boards & others painting not renewed.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

R. P. Saw (E.E)

Designature:-

Sahendra Rajak (A.E)
Flying Squad No. 2
(R.W.D)

28/11/21

(Signature)

28.11.21