

Date of Inspection: 28.11.21		District: Gaya
Division: Tikari		Length (km):
Name of the Road: Lo27 To Manikpur		
Scheme/Programme: HTSNY (Maintenance)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- It is small pcc road. Earthwork in flank is needed due to maintaining its level. In part area pcc. surface is roughened in which repair work is in progress.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	-
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- It should be maintained properly		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- R.P. Saw (E.E)

Designature:-

Sahendra Rajak (AE)

flying squad No-2

(R.W.N)

28/11/21

(Signature)

28.11.21