

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 29-11-2021		District: Muzaffarpur
Division : R.W.D, Muz. East - II		Length (km): 0.606 K.M.
Name of the Road: Gumbhawanpur Asit Paswan ki ghata to Mahadali Tolga Brahmasenan tar.		
Scheme/Programme: M.M.G.S.Y (SC)		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T & C.C.	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- B.T Surface damaged & wash out due to over top flood water at ch-250 to 275m, 4m to 430m C.C. Surface is satisfactory		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	N.A
Observation Remarks:- N.A		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road Furniture, Informatory Board, K.M. Post and 200 M Post is fixed in road.		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-
Designature:-

Rafresh Paswan
E.E.

ABUL
29/11/21
AB

29/11/2021
(Signature)