

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 28.11.21 District: Araria
 Division : Forbisgang Length (km): 1.850
 Name of the Road: Bihari Mandal Posdaha to Suryanarayan Yadav Mukhiya talga
 Scheme/Programme: MMGSY (ST)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:-

Pot holes and longitudinal cracks in RT portion
 Raincut in flank

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S

Observation Remarks:-

HP culvert is not painted

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	


Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Pramod Kumar

Designature:- EE, RWD, Reg. lab, Sasaram


 28/11/21
 EE

1 km
 28/11/21
 EE

(Signature)

EE, RWD, W. Div. - Forbisgang - Sri Anand Prakash