

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 27.11.2021	District: Arakudi
Division : Forbisganj	Length (km): 2.40
Name of the Road: Y. D. Tola Satsang Bhawan To Mushahari Tola	
Scheme/Programme: MMGSY (ST)	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:-

Rain cut in flank
unadequate flank in pcc part

2. Cross Drainage

a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S

Observation Remarks:-

3. Road Furniture

a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
----	---	---

Observation Remarks:-

4. Compliance History

a)	Status of ATR's & any others	
----	------------------------------	--

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Pramod Kumar

Designation:- EE, R. Lab Sonaram

EE, RWD, W. D. V. Forbisganj - Sanjay Prakash

(Signature)
27/11/21