

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 28.11.21		District: Araria
Division : Forbisgang		Length (km): 1.54
Name of the Road: Durgapur Tamgang path near Nityanand Gupta house to Kailash		
Scheme/Programme: Rishidai Tola MMAS (SC)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
<b>Observation Remarks:-</b> Raincut Flank at some part inadequate flume in part		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S
<b>Observation Remarks:-</b>		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
<b>Observation Remarks:-</b>		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Pramod Kumar

Designature:- EE, RWD, Reg. Lab, Sasaram

EE, RWD, W.O.N. - Forbisgang - Sri Anand Prakash

(Signature)