## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 29-11-7021	District: Musafferbu	
Division	: R.W.D. Mug. Econ. D.	11000 11.0	Y YOYK done 340M)
Name of	the Road: Mehrand Boxo		01670 7 39010
Scheme	Programme: GTSNY	100 10 1111031	
Sl. No.	The state of the s	to be checked	Remarks (S/U)
1.	Pavement C.		
a)	Condition of Surfacing		5
b)	Riding Quality		S
c)	Road Camber		5
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		5
e)	Contraction Joints provided or not (CC Pavement)		S
f)	Compaction of flank/slope & raincuts if any		S
2.	Cross Drainage		
a)	Condition of head walls in Hume p	pipe culverts including its painting	N.A.
b)	Condition of Abutment & Wing w	alls, Slab in RCC culverts	N· A
c)	Condition of railings/slab/approach for Bridges		N. A
d)	Condition of Vent Clearance		N·A
Observ	ation Remarks:-	Α.	
3.	Road Furniture		
a)	Whether sign boards/informatory stones/Pavement road markings ar	//cautionary Board/ km & 200m re provided and maintained	S
Observa	ation Remarks:- Road Furing	Hure, Intormatory Board.	vd, KM. POSA
4.	Compliance History		Section 1997
a)	Status of ATR's & any others		
Overall	Rating : Satisfactor	ry (S)/ Unsatisfactory (U)	S

0,0101	Satisfactory (S)/ Unsatisfactory (U)		
		1. 6.	
	o in och pastron	C 20 2	~

Name of Officer:- Ratnesh Passican

Designature:- E.E

(Signature)

ALS WE 29/11/21 AE