## INSPECTION REPORT FOR ROUTINE MAINTENANCE

	Inspection: 25.11.21 District:	Avari	9	
Division	Denger (		0	
	Programme: MMGSY(SC)	019		
Sl. No.	Parameters to be checked			Remarks (S/U)
1.	Pavement			
a)	Condition of Surfacing			S
b)	Riding Quality			3
c)	Road Camber			S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		exposed	-
e)	Contraction Joints provided or not (CC Pavement)			-
f)	Compaction of flank/slope & raincuts if any			U
a)	Condition of head walls in Hume pipe culverts including its painting		painting	U
2.	Cross Drainage			
			ointina	11
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		diffilig	
c)	Condition of railings/slab/approach for Bridges			_
d)	Condition of Vent Clearance			S
3.	Parapet of HP cultured not  Road Furniture	painted		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained			5
Observ	ation Remarks:-	An Laboratory		
4.	Compliance History			
a)	Status of ATR's & any others			
Övera	ll Rating : Satisfactory (S)/ Unsat	tisfactory (II)		4
Design	of Officer: - Pramod Kumar nature: - EE, Rwp, R. lab, Savaram Rwp, W. Div Forbisgang - Sri Aonal Pra	Q Alubo	ณ	nature)