ate of T-	INSPECTION REPORT FO	R ROUTINE MA	INTENAN	<u>CE</u> (14)
	26. 11. 21	71		
Xavi			1	
ame of	inchoad: Changian and a	Kattauria	00Z F3	
	MMGCV (CC)			
I, No.	Parameters to be	Shecked		Remarks (S/U
17.	Pavement	CHCCK D		
a)	Condition of Surfacing		2	
b)	Riding Quality		S	
c)	Road Camber			
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
e)	Contraction Joints provided or not (CC Pavement)			
f)	Compaction of flank/slope & raincuts if any			U
	ntion Remarks:- Compachin of flank slope 13.T. Suface is satisfa	eloy.	The Lord Land	THE TOTAL STREET
2. :	Cross Drainage			And the
a)	Condition of head walls in Hume pipe culverts including its painting		<u> </u>	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			
d)	Condition of Vent Clearance			5
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained			2
Observa	tion Remarks:-	•,		
4.	Compliance History	And And the second		
a)	Status of ATR's & any others			The state of the s
Overall		Unsatisfactory (U)		2
Name of Designat	Officer:- R.P. SAW (E.E.			P26.11.21