

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 26.11.2021	District: Araria
Division : Darbhanga	Length (km): 2.670
Name of the Road: Mathura Bazar To Shekhpura Nawal Das Tola	
Scheme/Programme:	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	U

**Observation Remarks:-** At some stretches flank were not proper.

2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

**Observation Remarks:-**

3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

**Observation Remarks:-**

4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) Satisfactory (S)

Name of Officer:- Pramod Kumar

Designature:- EE, RWD, R. Lab. Saranam  
EE, RWD, N. Dero Darbhanga. Sri Anil Prakash

26/11/2021  
AE

26/11/21  
EE  
(Signature)