

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 28.11.21	District: Araria
Division : Forbisgang	Length (km): 2.810
Name of the Road: Mathura North ward No-06 Near Saroj Jha House to Pawan to 19 No-3 via syphon	
Scheme/Programme: NABARD	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

**Observation Remarks:-**

Raincut in flank at some part  
unadequate flank in pce portion due to put. land

2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S

**Observation Remarks:-**

3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

**Observation Remarks:-**

4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	


Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)


S

Name of Officer:- Pramod Kumar  
Designature:- EE, RWD, Reg. lab, Sasaram

EE, RWD, W. Div.-Forbisgang - Sri Anmol Prakash

  
 28/11/21  
 AE

(Signature)

  
 28/11/21  
 EE