

INSPECTION REPORT FOR ROUTINE MAINTENANCE

(22)

Date of Inspection: 29.11.21 District: 9999
 Division: Tikari Length (km): 2.721 K.M
 Name of the Road: L039 Panchanpur mysi Road L083 to Dighour (V.R. 19)
 Scheme/Programme:

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	U
f)	Compaction of flank/slope & raincuts if any	

Observation Remarks:-

from ch. 0 to 2.1 - B.T. - Patch filling with bituminous material is in progress. Almost repair work is in progress. Compaction of flank/slope not maintained.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

R.P. Saw (E.E)

Designature:-

Sahendra Rajak (AE)

Flying Squad No-2
(R.W.D.)

29/11/21

(Signature)