

INSPECTION REPORT FOR ROUTINE MAINTENANCE

(18)

Date of Inspection : 25.11.21		District: 499
Division : Tileqvi		Length (km): 0.973 K.M
Name of the Road: L042 wireless Bagahi Road to mazhouli (Vr. 42)		
Scheme/Programme: PMGSY (Maintenance)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- few patches developed on the B.T. surface which needs repair. Repair work is in progress. Compaction of flank/slope is not maintained.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- 		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- properly not maintained.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

R. J. Saw (E.E)

Designature:-

Sahendra Rajak (AE)

Flying Squad No. 2

1 R W D 7

RJP

25/11/21 (Signature)

25.11.21