

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 1656 अत्र

दलसिंहसराय / दिनांक 14/09/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय- **New Maintenance Policy 2018(MR New)** योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान हेतु **Rs.-40.00 (Forty Lakh Rupess)** की आवश्यकता है। अधियाचना का निर्माण कार्य विशिष्टियों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-40.00 (Forty Lakh Rupess)** उपलब्ध कराने की कृपा की जाये।

- अनु०- 1) अधियाचना प्रपत्र।
2) 19 ए फॉर्म।
3) IRI Report की छायाप्रति संलग्न।

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

14/09/21

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PU(Dalsinghsarai)

Sl. No.	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RL (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	Up to date expenditure as per MIS (in Lac)	Expenditure Against work done (in Lac)	Remaining
					Length (in Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in Lac)	5 years Routine Maintenance (in Lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1		NH 28 Gangapur se Morwa Prachand Tak	10105081		2.70	89.73630	51.11770	25.66672			-	3887	25mm	5.10%	0.00000	0.00000	40.00000	
2		NH 28 Panstala Se Rupsoli Graw Tak	10105087	1855	1.90	64.56830	33.46031	17.86070			-	3928	25mm	5.10%	26.76800	26.76800	0.00000	
3		Patel chowk se Ghaighan sabhi ke ghar panghi tola hote hote Mahesi karpuri banahi tak pakki road nirman	32010401024	24.06.2019	3.50	118.73710	67.17413	35.41076			-	3767	25mm	5.10%	67.17400	66.79885	0.00000	
4		Raipur Bazar se Bhulbhadrapur Mesli Tak	10105082		3.50	118.41100	66.46896	34.87598			-	3902	25mm	5.10%	53.17520	53.17520	0.00000	
					11.600	391.453	218.22110	113.81416							147.11720	146.74205	40.00000	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to date Physical Progress has been uploaded in MIS.

Sr Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)

Form of Utilisation Certificate upto August 2021

New Maintenance Policy 2018(MR New)

PIU:- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	1367.95492	1367.95492	Certified that out of Rs-1367.95492 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-1352.62628 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-15.32864 Lakh remaining unutilized at the end of period under the time of completion
		1367.95492	1367.95492	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was


Kind of Checks Exercised:-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurments have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have overserved

3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works


Sr.DAO
Rural Works Department,
Works Division Dalsinghsarai



Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai
14/05/21

Date	Time	Test No	Distance (meter)	Total distance (m)	BUMP (cm)	Speed (Km/Hr)	U/I (mm/Km)	Corrected U/I (mm/Km)	IRI (mm/Km)	Status	Latitude	Direction	Longitude	Direction	Remarks
8/9/2021	4:39:44 PM	16	100	100	28	3.3 Km/Hr	2800	2844	3841	G	25.81356	N	85.69514	E	Normal
8/9/2021	4:40:16 PM	16	100	200	30	11.4 Km/Hr	3000	3022	4055	A	25.81356	N	85.69514	E	Speed Breaker
8/9/2021	4:42:04 PM	16	100	300	26	3.2 Km/Hr	2600	2666	3626	G	25.81356	N	85.69514	E	Normal
8/9/2021	4:42:43 PM	16	100	400	28	9.0 Km/Hr	2800	2844	3841	G	25.813291	N	85.6951	E	Normal
8/9/2021	4:43:25 PM	16	100	500	26	8.6 Km/Hr	2600	2666	3626	G	25.813291	N	85.6951	E	Normal
8/9/2021	4:44:07 PM	16	100	600	25	8.4 Km/Hr	2500	2578	3518	G	25.813291	N	85.6951	E	Speed Breaker
8/9/2021	4:44:36 PM	16	100	700	24	12.6 Km/Hr	2400	2489	3410	G	25.81161	N	85.69569	E	Normal
8/9/2021	4:46:03 PM	16	100	800	28	4.2 Km/Hr	2800	2844	3841	G	25.809445	N	85.69652	E	Normal
8/9/2021	4:52:35 PM	16	100	900	25	0.9 Km/Hr	2500	2578	3518	G	25.810386	N	85.70065	E	Normal
8/9/2021	4:53:08 PM	16	100	1000	32	11.0 Km/Hr	3200	3200	4267	A	25.810386	N	85.70065	E	Speed Breaker
8/9/2021	4:53:31 PM	16	100	1100	24	15.5 Km/Hr	2400	2489	3410	G	25.812692	N	85.70165	E	Normal
8/9/2021	4:53:52 PM	16	100	1200	30	17.2 Km/Hr	3000	3022	4055	A	25.812692	N	85.70165	E	Speed Breaker
8/9/2021	4:54:13 PM	16	100	1300	29	17.0 Km/Hr	2900	2933	3948	G	25.813405	N	85.70316	E	Normal
8/9/2021	4:54:33 PM	16	100	1400	22	17.6 Km/Hr	2200	2311	3191	G	25.813405	N	85.70316	E	Normal
8/9/2021	4:54:56 PM	16	100	1500	29	15.9 Km/Hr	2900	2933	3948	G	25.813405	N	85.70316	E	Speed Breaker
8/9/2021	4:55:22 PM	16	100	1600	24	13.8 Km/Hr	2400	2489	3410	G	25.815581	N	85.70522	E	Normal
8/9/2021	4:55:47 PM	16	100	1700	32	14.5 Km/Hr	3200	3200	4267	A	25.815581	N	85.70522	E	Speed Breaker
8/9/2021	4:56:21 PM	16	100	1800	34	10.6 Km/Hr	3400	3378	4478	A	25.815581	N	85.70522	E	Speed Breaker
8/9/2021	4:56:57 PM	16	100	1900	28	9.9 Km/Hr	2800	2844	3841	G	25.815581	N	85.70522	E	Normal
8/9/2021	4:57:33 PM	16	100	2000	29	10.1 Km/Hr	2900	2933	3948	G	25.815581	N	85.70522	E	Speed Breaker
8/9/2021	4:59:33 PM	16	100	2100	28	10.1 Km/Hr	2800	2844	3841	G	25.815581	N	85.70522	E	Normal
8/9/2021	5:03:33 PM	16	100	2200	32	10.1 Km/Hr	3200	3200	4267	A	25.815581	N	85.70522	E	Speed Breaker
8/9/2021	5:07:38 PM	16	100	2300	27	10.1 Km/Hr	2700	2755	3734	G	25.815581	N	85.70522	E	Normal
8/9/2021	5:14:12 PM	16	100	2400	32	10.1 Km/Hr	3200	3200	4267	A	25.815581	N	85.70522	E	Speed Breaker
8/9/2021	5:18:33 PM	16	100	2500	35	10.1 Km/Hr	3500	3467	4584	A	25.815581	N	85.70522	E	Speed Breaker
8/9/2021	5:24:12 PM	16	100	2600	29	10.1 Km/Hr	2900	2933	3948	G	25.815581	N	85.70522	E	Normal
8/9/2021	5:29:30 PM	16	100	2700	32	10.0 Km/Hr	3200	3200	4267	A	25.815581	N	85.70522	E	Speed Breaker

8/16/21

14-9-21

Name of Contactor- Ratnesh Construction Pvt Ltd
Name of Work- NH 28 Gangapur se Morwa Prakhand Tak



Handwritten signature
 16/11/20