

R.W.D.(W) Sub Division, Katra (Muzaffarpur)					
NAME OF WORK		Constriction of bridge of size 3X16.00 m. Over Chakbhagda river in Basant to Singhwara road of Katra block in Muzaffarpur Dist.			
Sl.No.	Description of Work	Unit	Qty.	Rate per Unit	Amount
1	Supplying ,laying & spreading of Brick bats etc.complete job as per specification and direction of E/I.	M ³	131.30	2272.66 2064.56	271077.00 298400
2	Providing and laying Reinforced cement concrete pipe NP3 1000 mm dia as per design in single Row.	M ³	15.00	4366.05 4116.28	65490.00 61744
Grand Total Rs.					336567.00

23/11/21
JE(RWD) Muz. East-2

23.11.21
AE(RWD) Muz. East-2

23/11
EE(RWD) Muz. East-2

Say 3. 366 lacs

GENERAL ABSTRACT

Name of road Constriction of bridge of size 3X16.00 m. Over Chakbhagda river in Basant to
Singhwara road of Katra block in Muzaffarpur Dist.
District Muzaffarpur
Block Katra
Division Muzaffarpur East -2
Lenth of Road(in KM)

SL.NO.	DESCRIPTION	AMOUNT (IN LAKHS)
1	Brick Bats	2.98
2	Sand	3.366
3	Hume Pipe	0.62
GRAND SUB TOTAL		3.60

[Signature]
23/12/21
JE(RWD) Muz. East-2

[Signature]
23.12.21
AE(RWD) Muz. East-2

[Signature]
23/12/21
EE(RWD) Muz. East-2

As Per S.E. RWD (W) Circle Muz.
Letter No 1170 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD (W) Division East-1, Muz.

Technically Sanctioned for Rs. 3.366 Lacs
(Rs. Three lacs thirty six thousand six
hundred) only (provisionally)

[Signature]
24/12/21
Superintending Engineer
Rural Works Department
Work Circle: Muzaffarpur
[Signature]
24.12.21

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar

2. Name of Block/Road - Katta/Construction of bridge of size 3x16.00m over Chakbhagda River in Barunt to Singhwara road of Katta block in muzaffarpur dist.

A. For Road

1. Damage Location/Chainage : ~~0.1010m to 0.12361m~~
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
i. Material being used in Restoration works :
ii. Equipments/Tools being used in Restoration works:
iii. Procedure taken up in Restoration works :
iv. Restored Length :

B. For Bridge

1. Damage Location/Chainage : 0.1010m, 0.12361m
2. Damage Length : 0.0236km
3. Nature of Damage : Flood
4. Details of Restoration Works :
i. Material being used in Restoration works : brick bats - 131-30 m²; HP - 15 m
ii. Equipments/Tools being used in Restoration works: Tractor more done satisfactory
iii. Procedure taken up in Restoration works :
iv. Restored Length : 0.0236km

Signature of JE/AE/EE

Signature

(Name of Inspector)

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1