

R.W.D.(W) Sub Division, Katra (Muzaffarpur)					
NAME OF WORK		Bari kothi se Tehwara Panchayat Hote Hue singhwara tak(Barri chowk se khaura pul)			
Sl.No.	Description of Work	Unit	Qty.	Rate per Unit	Amount
1	Supplying ,laying & spreading of Brick bats etc.complete job as per specification and direction of E/I.	M ³	586.500	2064.56 2155.45	1210864.00 1264171
Grand Total Rs.					1264171

1210864.00

[Signature]
JE(RWD) Muz. East-2

[Signature]
AE(RWD) Muz. East-2

[Signature]
EE(RWD) Muz. East-2

Rs. 12.11 lacs

GENERAL ABSTRACT

Name of road

Bari kothi se Tehwara Panchayat Hote Hue singhwara tak(Barri chowk se khaura pul)

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East -2

Lenth of Road(in KM)

SI.NO.	DESCRIPTION	AMOUNT (IN LAKHS)
1	Brick Bats	42.64 12.11
2	Sand	
3	Hume Pipe	0.00
GRAND SUB TOTAL		42.64 12.11

dh
JE(RWD) Muz. East-2

24.11.21
AE(RWD) Muz. East-2

24/11
EE(RWD) Muz. East-2

As Per S.E. RWD (W) Circle Muz

Letter No 1179 Dated 01/10/2021

Estimate has been verified by inspecting

E.E. RWD. (W) Division 1442 East-1

Technically Sanctioned for Rs. 12.11 Lacs (Rs. Twelve Lacs eleven thousand) only (provisionally)

24.12.21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- Gyan vibhakar
2 Name of Block/Road- Kothri/Balti kothi se rehwalai panchayat hose hue Singhwata tak
(Barri chowk se Kharabul)

A For Road

- 1 Damage Location/Chainage 0.030 km, 0.200 km, 0.800 km, 1.000 km
2 Damage Length 0.746 km
3 Nature of Damage
4 Details of Restoration Works-
i Material being used in Restoration Works- Bricks - 586.80 m³ morden
satisfactory
ii Equipments/Tools being used in Restoration Works- Tractor
iii Procedure Taken up in Restoration Works-
iv Restored Length 0.746 km

B For Bridge

- 1 Damage Location/Chainage
2 Damage Length
3 Nature of Damage
4 Details of Restoration Works-
i Material being used in Restoration Works-
ii Equipments/Tools being used in Restoration Works-
iii Procedure Taken up in Restoration Works-
iv Restored Length

Signature of JE/ AE/ EE

Signature

(Name of Inspector)

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल, मुजफ्फरपुर 221101