

R.W.D.(W) Sub Division, Katra (Muzaffarpur)					
NAME OF WORK		REO Sadak se Ufrauli Chawk to Changel Mliyavari Chauk tak			
Sl.No.	Description of Work	Unit	Qty.	Rate per Unit	Amount
1	Supplying, laying & spreading of Brick bats etc. complete job as per specification and direction of E/I.	M ³	444.70	2064.56 2272.60	9,18,110.00 1010652
Grand Total Rs.					1010652

Say 9.18.22

[Signature]
JE(RWD) Muz. East-2

[Signature] 22/11/2021
AE(RWD) Muz. East-2

[Signature]
EE(RWD) Muz. East-2

GENERAL ABSTRACT

Name of road

REO Sadak se Ufrauli Chawk to Changel Mliyavari Chauk tak

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East -2

Lenth of Road(in KM)

SI.NO.	DESCRIPTION	AMOUNT (IN LAKHS)
1	Brick Bats	10.11
2	Sand	9.132 lay
3	Hume Pipe	
GRAND SUB TOTAL		10.11

due
22/11/21
JE(RWD) Muz. East-2

22.11.21
AE(RWD) Muz. East-2

22/11/21
EE(RWD) Muz. East-2

As Per S.E. RWD (W) Circle Muz.
Letter No 1179 Dated 6/10/2021
Estimate has been verified by inspecting
E.E. RWD (W) Division Muz. East-2

Sanctioned
Technically Appraised for Rs. 9.132 lay
Rs. Nine lac eighteen thousand two
hundred) only (provisionally)

24.12.21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar

2. Name of Block/Road - katha / R/O Sadak se Uftauli Chowk to chander mliavari
Chauk Tak

☒ A. For Road

1. Damage Location/Chainage : 0.500 km to 0.790 km

2. Damage Length : 0.2898 km

3. Nature of Damage : Flood

4. Details of Restoration Works :

- Material being used in Restoration works : Brick bats - 444-70mm³ work done satisfactory
- Equipments/Tools being used in Restoration works : Tractor
- Procedure taken up in Restoration works :
- Restored Length : 0.2898 km

☒ B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

- Material being used in Restoration works :
- Equipments/Tools being used in Restoration works:
- Procedure taken up in Restoration works :
- Restored Length :

Signature of JE/AE/EE

Signature

(Name of Inspector)
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1