

R.W.D.(W) Sub Division, Katra (Muzaffarpur)					
NAME OF WORK			Basant se Chakhaji Hute Hue to Baganl Tak		
Sl.No.	Description of Work	Unit	Qty.	Rate per Unit	Amount
1	Supplying ,laying & spreading of Brick bats etc.complete job as per specification and direction of E/I.	M ³	415.89	2064.56 2272.66	858629.86 945177
Grand Total Rs.					945177

Rs. 8.587 lacs

22/11

Janu
22/11/22
JE(RWD) Muz. East-2

At 22/11/22
AE(RWD) Muz. East-2

EE(RWD) Muz. East-2

GENERAL ABSTRACT

Name of road Basant se Chakhaji Hute Hue to Bagani Tak
District Muzaffarpur
Block Katra
Division Muzaffarpur East -2
Lenth of Road(in KM)

SI.NO.	DESCRIPTION	AMOUNT (IN LAKHS)
1	Brick Bats	9.45
2	Sand	8.587 lakhs
3	Hume Pipe	
GRAND SUB TOTAL		9.45

Signature
JE(RWD) Muz. East-2

Signature
AE(RWD) Muz. East-2

Signature
EE(RWD) Muz. East-2

As Per S.E. RWD (M) Circle Muz.
Letter No 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD. (M) Division Muz East-1

Technically *Sanctioned* for Rs. 8.587 lakhs
(Rs. Eight lakhs fifty eight thousand seven
hundred) only (provisionally)

Signature
24/2/21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - Katra/Basant se chaknaji Hute Hue to Baguni Tak

A. For Road

1. Damage Location/Chainage : 0.10.1m to 0.1382 km
2. Damage Length : 0.0382 km
3. Nature of Damage : Flood
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick badd - 45-89 m² work done satisfactory
 - ii. Equipments/Tools being used in Restoration works : Tractor
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.0382 km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

(Name of Inspector)

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल, मुजफ्फरपुर पूर्व-1