



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR



| | | | |
|------------------------|----------------------------------|---------------------------|---------|
| Name of the Road :- | T08 Daulatpur Gurmiya South Tola | | |
| DISTRICT | Vaishali | | |
| DIVISION | Hajipur | | |
| BLOCK | Hajipur | | |
| DAMAGED LENGTH OF ROAD | : | 0.250 | 250M KM |
| CONSTRUCTION COST | : | 2.641 2.579 | Lac |

Submitted By :-
Executive Engineer
RWD Work Division, Hajipur

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- R.W.D works Division, Hajipur

2 Name of Block/Road :- Hajipur / Tos Daulatpur - Gurmiya South tola

(A) For Road:

1. Damage Location/Chainage :- 0.400, 0.460,
2. Damage Length :- 250m
3. Nature of Damage :- Wash out side embankment
4. Details of Restoration Works :- ECB → 600 No, Bamboo pile → 50 No, Bamboo Run → 50
- (i) Material being used in Restoration works:- Bamboo piles, ECB with local sand.
- (ii) Equipment's/Tools being used in Restoration works:- Tractor, Tolly
- (iii) Procedure taken up in Restoration works:
- (iv) Restored Length :- 50m

WORK IS Satisfactory.

(B) For Bridge:

N/A

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length :-

Signature of JE/AE/EE

S.K.
27.11.21

Sanjay
27.11.21

AE
Sanjay

Signature

(Name of Inspection)

GENERAL ABSTRACT

Name of Road T08 Daulatpur Gurniya South Tola

District Vaishali

Block Hajipur

Division Hajipur

Length of Road (in Km)

0.250 Km

| Sl. No. | DESCRIPTION | AMOUNT (LAKHS) |
|---------|-----------------|----------------|
| 1 | Earthwork | |
| 2 | Brick Bats | 0.000 |
| 3 | Sand Filling | 0.000 |
| 4 | Sand bag | 0.000 |
| 5 | Bamboo Piles | 2.6068 -2.531 |
| 6 | bamboo runners | 0.02675 -0.032 |
| 7 | H.P. | 0.00823 -0.016 |
| | SUB TOTAL | 0.000 |
| | GRAND SUB TOTAL | 2.641 -2.579 |
| | | 2.641 -2.579 |

S/A
27.11.21
RWD

Sanjiv
27.11.21
AE
RWD

Jan
09/11
EE
RWD

As Per S.E. RWD (M) Circle Muz
Letter No 1178 Dated 01/10/2021
Estimate has been verified by inspecting
E. E. RWD. (M) Division Muz west

Technically Sanctioned for Rs. 2.641 Lacs
(Rs. Two lacs Sixty four thousand one
hundred) only (provisionally)

W
27.12.21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur
27.12.21

| SI. No. | SDB SL NO | MORD Ref. No | Description | Unit | QUANTITY | RATE | AMOUNT (in Rs.) |
|----------------------|-----------------|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-----------------|---------------|--------------------|
| 1 | | WRD 5.7.40 | Sand bag Providing including labour for filling empty cement bag with local sand, stitching the bag and placing including supply of sutali etc. all complete as per approved design, specification and direction of E/ As Per MB No- 2819 & Page No- 4 | Nos | 6618 | 39.39 | 260683.02 |
| | | | | Total | 6,618.00 | -38.25 | -253138.50 |
| 2 | | WRD 5.7.7 | Labour for cutting and fixing of 62 mm to 75 mm dia bamboo piles to size and making shoes and driving etc. complete job as per specification and direction of E/ As Per MB No- 2819 & Page No- 3 | M | 50 | 53.51 | 2675.50 |
| | | | | Total | 50.00 | -64.06 | -3203.00 |
| 3 | | WRD 5.7.9 | Labour for fitting and fixing 62 mm to 75 mm dia bamboo runners in position at every verticle pile with 150 mm long nails or 38 swg G. I. wire including cost of G.I. or nails complete job as per specification and direction of E/ As Per MB No- 2819 & Page No- 3 | M | 50 | 16.46 | 823 |
| | | | | Total | 50.00 | -31.83 | -1691.60 |
| Total Cost :- | | | | | | | -257933.00 |

264181.52

Sr
27.11.21
J.E

Dom
11/11/21