

57

1-7-11

Scanned with CamScanner

of Work-
 uation of Work-
 Agency by which work is executed-
 Date of Measurement-
 No. and date of agreement

(These four lines should be repeated at the commencement
 of the measurement relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
RECORD ENTRY					
Name of Work - Emergent Repair for					
Restoration of Traffic for					
Flood damaged/ Heavy rain					
Road from Panabur to					
Harizon Tola Narha					
under - F.D.R (Year - 2021-22)					
Authority - E.E. R.W.D (W) DIV - Pakhdayal					

1. Providing brick bats

including spreading

laying labour - do -

pitching & operation

including light ramming

E.T. call complete Job -

C.H (K.m)	Measurement	Qty (m ³)
0.150 To 0.350	40.00 m x 2.0 x 0.500 =	40.00 m ³
	15.00 m x 1.00 x 0.450 =	6.75 m ³
	29.00 m x 1.00 x 0.600 =	17.40 m ³
0.400 To 0.560		
	11.00 m x 2.0 + 1.20	
	x 0.600 =	10.56 m ³
	2	

Continuation

[illegible]

ABSTRACT OF COST

- ① Providing brick bats including
Spreading laying labour...
do - pitching slope apron
including Light ramming
E.T.c all complete job —

Qty - Vide Tmb Page no. (2)

105.65 cm^3	①	$1938 = 89/\text{m}^3 R = 204844 = \text{ru}$	
		Sol $R = 2,04800 = \text{ru}$	

~~Calder~~
04/02/22
J.E

09.02.22

Continuation ...