

GENERAL ABSTRACT

Name of Road	Hathauri PWD Rd to Kafan Chaudhary	
District	Muzaffarpur	
Block	Bochaha	
Division	Muzaffarpur East-2	
Length of Road		
Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Brick Bats	9.946 9.04
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	9.946 9.04
TOTAL COST OF PROJECT IN LACS =		9.946 9.04

25/11/21
JE

25/11/21
AE

25/11/21
EE

As Per S.I. RWD (M) Circle Muz.
Letter No 1179 Dated 01/08/2021
Estimate has been verified by inspecting
E. E. RWD. (M) Division Muz. East-1

Technically sanctioned for Rs. 9.04 lacs
(Rs. Nine lacs four thousand) only
(provisionally)

28.12.21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur

28.12.21

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- RWD Works divn Muzaffarpur East 2

2 Name of Block/Road :- Bachahis.

Major Road: Hathausi PWD Rd to Kaben chandhary.


1. Damage Location/Chainage :- Many Locations
2. Damage Length :- 0.3489 km
3. Nature of Damage :- Breach of rd due to Flood
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats (437.6 m³)
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor
 - (iii) Procedure taken up in Restoration works:- Immediate restoration of rubble
 - (iv) Restored Length :- 0.3489 km.

(B) For Bridge:


1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Work found Satisfactory.

N/A.


Signature of JDA/EE




Signature

(Name of Inspection)