

Date:

Inspection Report for flood damage work

year (2021-22)

05.12.2021

Dhamdaha

1. Name of PIUs-

2. Name of Block/Road-

Rupauli - L028-Koul - Simra to Koshuipur
Near Maheshpur Kalihar Border (VR28)

A. For Road

1. Damage Location/Chainage :

2. Damage Length

: - 745 M

3. Nature of Damage

: side crust - cutting due to blood

4. Details of Restoration

i Material being used in Restoration

: Bamboo pile, sand bags, bricks, but

ii Equipment/Tools being used in Restoration works:

: tractor, JCB

iii Procedure taken up in Restoration works

: manual

iv Restored Length

: 745 m (749,73,388 = 0)

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length

3. Nature of Damage

4. Details of Restoration

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

Signature of JE/AE/EE

Signature

Executive Engineer
(Works) Division
PUNE

Executive Engineer,
Rural Works Department
Works Division Dhamdaha (Pune)

ABSTRACT OF COST

Name of Work :-		L028-Kouli Simra to Koshkipur Near Maheshpur Katihar Border (VR28)
Block :-		Rupauli
Sl. No.	Particulars	Amount (In Rs.)
A	Cost of Restoration work :-	Rs 4224817.00
B	Add 12 % GST	Rs 506978.00
C	Add 1 % L. Cess	Rs 42248.00
D	Add S.Fee @ 10 % of Material Cost	Rs 199345.32
Total Cost with GST, LC & S.Fee		4973388.00

8h
27/10/2021
J.E
RWD
Rupauli

Sum
27-10-2021
A.E
R.W.D
Rupauli

Q 27-10-21
E.E
R.W.D
Dhamdaha

Technically section for Rs. 4973388.00 (Fourteen lacs. seventy three thousand three hundred eighty eight) only.

W
8.12.21
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, पूर्णिया।

Sum
8.12.2021
A.E