

Inspection Report for Flood damage work (year 2021-22)

Date:

3-12-21

1. Name of PIUs-

Dhmdaha.

2. Name of Block/Road-

Rupauli/Tintonga Tola to Chorkar WABG.

A. For Road

1. Damage Location/Chainage :

2. Damage Length :

143 Mtr

3. Nature of Damage :

Side Canal cutting due to flood.

4. Details of Restoration :

i Material being used in Restoration

Sand Bag, Bamboo Pile, & Bricks etc

ii Equipment/Tools being used in Restoration works:

Tractor,

iii Procedure taken up in Restoration works

Manual.

iv Restored Length

143 Mtr (Rs. 9,17,898=)

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

Signature of JE/AE/EE

03-12-21
Executive Engineer,
Rural Works Department
Works Division Dhmdaha (Purnea)

Signature

(Name) Executive Engineer
(Designation) Division
PURNIA

Dhamdaha

DIVISION

Rupauli

SUB-DIVISION

Tintanga Tola to Choghay
wasa**MEASUREMENT BOOK**

No. 61

प्रमाणित किया जाता है कि इस मापी
पुस्तक में 1 से 50 पन्ने मुद्रित हैं। यह
मापी पुस्तक आवर प्रमंडल पहाडिकारी
रूपौली के नाम से निर्गत किया
जाता है।

Name of Officer

Date of first entry

Date of last entry

05.10.21
Executive Engineer

Rural Works Department

Works Division, Dhamdaha (Purnea)

05/10/21

Name of work—

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work	1/72	10	Phitsa	Timpahi	
Panchayat	42	Timpahi	70/9		
to Chorkay Wadai					
Authority	E.F.R.W.D. works				
	Division Phnom Penh				
① Labour for Deriving 62 mm to 75 mm of Bamboo Piles					
Incl. duty 82c & 8 hours etc. 1 day 10h.					
Ch. 20 to 330 M	1X	30	X	3.0 =	90M
	1X	30	X	3.0 =	90M

	1X	30	X	3.0 =	90M
	1X	20	X	3.0 =	60M
Ch. 545 to 578 M					
	1X	30	X	3.0 =	90M
	1X	3.0	X	3 =	9.0M
					429.0M

② providing, supply fitting and fixing of Bamboo 62 mm by 5 mm & Runner left side					
	1X	3X	30X	=	90M
	2X	3X	30	=	180M
	2X	1X	30	=	180M
Red.	1X	3X	30	=	90M
	1X	3X	3	=	9M
					429M

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) Supply fitting & fixing position of split bamboo woven chachori					
	2	30	1.5		90 m ²
	1	30	1.5		45 m ²
	2	30	1.5		45 m ²
	1	23	1.50		34.5 m ²
					214.50 m ²
(4) Left side 140 mtr size of canal bag					
		0.76	0.508	0.104	
Avg. depth - (0.25 × 2.20 + 2.75 + 1.70 + 0.75) / 5				5	
No of sand bag	143	1.50			
		0.76	0.104		

	2262	0.76	0.508	0.104	70.87 m ³
	1	2262			2262 m ³
(5) provide lay bricks duts including seprate work					
1. Hammer					
Well	2	30	(0.65 + 0.75 + 1.20 + 1.5)	5	
	2	30	1.80		
	2	30	(0.65 + 0.75 + 1.75 + 1.20 + 1.5)	5	
			(1.20 + 1.53 + 1.70 + 2.45)	5	
	2	30	1.180	1.50	106.20 m ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF WORK				
N/Work	FDR to Tindaya Dola to Chhachar area.				
Authority	E E R.W.D works Division Dhamdaha.				
①	Providing bamboo Piles. Including labour of cutting many bamboo piles EXCUTING BAMBUS				
	429 m P-①				
	e. 52.64/m —————				Rs. 22583.20

②					
Piering, fitting and fixing split bamboo woven dhalat.					
with 20 s.w.g. wire. do do comp job					
24.50 m ² P-②					
@ 458.11/m ² —————→ Rs. 9826.50					
③					
Supply fitting and fixing 62 m ⁴ to 75 m ⁴ of Bamboo Runer					
do do comp job.					
429 m P-①					
@ 30.12/m —————→ Rs. 12971.00					
④					
Plr long and specially bricks bats in ditches all comp job.					
253.11 m ³ P-③					
@ 2108.11/m ³ —————→ Rs. 55399.00					

Continuation

Rs 6,87,662.00

[illegible]

Scanned with CamScanner