



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FDR

FLOOD DAMAGED REPORT



Jurawanpur Taufir To Chakchand

DISTRICT	:-	Vaishali	
DIVISION	:-	Mahnar	
BLOCK	:-	Raghopur	
TOTAL LENGTH OF ROAD	:-	8.315	KM
PART-A TOTAL COST OF INTIAL RECTIFICATION IN SURFACE RENEUAL	:-	11.092 10.141	Lac
TOTAL COST OF PROJECT	:-	11.092 10.141	Lac

Inspection Report for Flood Damage Report

Date :

1 Name of PIUs

2 Name of Block/ Road

- Raghobpur / Jaisamampur Tansfir to Chalsand.

A. For Road

1 Damage Location/Chainage

: Near culvert & chainage 3200

2 Damage Length

: 183.29

3 Nature of Damage

: Surface, Bridge, Sub base & embankment

4 Details of Restoration Works

: Bottle Bricks 516.92 m

i. Material being used in Restoration works

: Brick bats, Satisfactory

ii. Equipments/Tools being used in Restoration works

: Tractor, T.C.B

iii. Procedure taken up in Restoration works

: only motorable work has been done.

iv. Restored Length

: 183.29

B For Bridge

: NA

1 Damage Location/Chainage

:

2 Damage Length

:

3 Nature of Damage

:

4 Details of Restoration Works

:

i. Material being used in Restoration works

:

ii. Equipments/Tools being used in Restoration works

:

iii. Procedure taken up in Restoration works

:

iv. Restored Length

:

Signature of JE / AE / EE

Signature of JE / AE / EE


Signature
(Name of Inspector)


Executive Engineer
R.W.D. Works Division
Hajipur


प्रतिवेदन

1. पथ का नाम :- 1038 जुड़, 1975 जुड़ तो फिर 14-जड़-पॉफ
2. पथ की लम्बाई :- 8.315 km
3. प्रखण्ड का नाम :- रावोपुर
4. क्षतिग्रस्त की लम्बाई :- 183.29 म
5. प्राक्कलित राशि :- 10.141 211 19
6. वर्ष-2021 का बाढ़ एवं अतिवृष्टि :- 916

यह प्राक्कलन उक्त पथ के वर्ष-2021 में आई बाढ़/अतिवृष्टि के कारण
चैनेज 300.40350 m, 410.40470, 825.40865, 1230.401263.29 m चैनेज
कुल 183.29 मीटर में पथ की हुई क्षति के अस्थायी मरम्मत/पुनर्स्थापन कार्य का है।
इस मूल पथ की कुल लम्बाई-8.315 कि०मी० है। यह पथ पंचवर्षीय अनुरक्षण अवधि
के अन्दर/बाहर है। इस प्राक्कलन में कराये गये अस्थायी मोटरबुल कार्य मद आदि
सम्मिलित है। क्षतिग्रस्त कार्य MIS पर अंकित है तथा इसके फोटोग्राफ लिये जा चुके
हैं, जो संलग्न है। कराये जाने वाले कार्य के दर वर्तमान चालू अनुसूचित दर पर
आधारित है। यह प्राक्कलन विभागीय पत्रांक-4555, पटना, दिनांक-05.11.2021 एवं
विभागीय पत्र संख्या-4589, दिनांक-13.11.2021 से प्राप्त निदेशानुसार तैयार किया गया
है। यह पथ MIS के 33 गांव 350 अंकित है


कनीय अभियंता


सहायक अभियंता


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, महनार।

FLOOD DAMAGED REPORT

GENERAL ABSTRACT OF COST

Block:-- Raghopur

District:- Vaishali


Length of Road:-- 8.315 KM

Name of Road:-- Jurawanpur Taufir To Chakchand

SL. No.	Item of Work	Amount
A	TOTAL COST OF CONSTRUCTION	: 11.092 10.141 Lacs
	TOTAL	: 10.141 Lacs

11.092


3/11/21
Junior Engineer



29/11/21
Asstt. Engineer


Executive Engineer

SE
RWD

Technically Approved Rs. 11.092 lacs (Rs. Eleven lacs
nine thousand two hundred) only

Page 2


18/12/21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur

Schedule XLV-Form No. 134

MAH NAR

DIVISION

RAGHOPUR

SUB-DIVISION

Measurement Book

- 823

जुड़ावनपुर मो.फिर से चक्र-चाँह

1st on the list

of work -
 tion of work -
 cy by which work is executed -
 of measurement -
 and date of agreement.
 (four lines should be repeated at the commencement
 measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of road in Jhauwarpur Taluqa to a black channel in Ranghopur block of H. D. R.					
Agency -					
Date of entry -				18/10/21	
2. Providing brickbats including binding, bedding & hand packing with with H.C. P. Hume					
In all comb' jobs					
Start of from chimney of Amarkul					
$3.65 \times 1.82 \times 0.225 =$					1.49 m
$2.43 \times 1.21 \times 0.225 =$					0.66
$2.74 \times 3.05 \times 0.225 =$					1.88
$2.74 \times 0.91 \times 0.225 =$					0.56
$2.13 \times 2.43 \times 0.225 =$					1.16
$0.60 \times 0.30 \times 0.225 =$					0.045
$8.23 \times 3.65 \times 0.225 =$					6.75
$2.65 \times 0.91 \times 0.100 =$					0.332

Continuation

12.87 m

Sl. No.	Details of actual measurement				Contents of area
	No.	L.	B.	D	
				B.F. pty =	18.87
	20.74	16.40	2.075		1.32
	3.05	3.05	1.100		0.93
	6.40	2.05	1.150		1.42
	4.26	2.74	0.200		2.33
	5.15	3.05	1.225		3.55
	3.65	2.74	0.250		2.50
Near H.A. cut/vet. along road					
	30.0	3.25 + 2.05		0.2	1.52
					116.64
	5.18	3.05	2.300	100	3.16
					144.72
					118
					18
					0.21
					4.24

Recd entry

Date of entry - 22/10/21

9th - Profit & Loss Brick hole
in study boundary &
road corner

in all count job,

$$5.18 \times 3.65 \times 0.225 = 9.06$$

$$2.13 \times 3.65 \times 0.250 = 1.94$$

$$1.52 \times 1.21 \times 100 = 0.18$$

$$1.52 \times 1.21 \times 0.100 = 0.18$$

$$1.82 \times 1.21 + 0.91 \times 0.200 + 1.00$$

$$= 0.29$$

$$11.65$$

C/D

Continuation

Continuation

Sl. No.	Details of actual measurement			Contents of area
	No.	L.	B. D.	
			B.P. 04-	10.20
			near school -	
		$30.00 \times 4.20 + 4.25 \times 0.300 + 0.60$		
		2		2
				$= 98.43$
				148.624
				28/10/21
				7.22

Recedent

Dated entry - 28/10/21

16/1 Priority & Paving Brick

bulk include 8% wastage

& level paving -

in all cement jobs

measured as follows -

$1 \times 140 \times 4.2 + 3.25 \times 0.250 + 0.700$

2

2

near school

$= 38.824$

$16 \times 4.25 + 3.75 \times 0.600 + 0.300$

2

2

3m deep brick

$= 28.83$

$12 \times 4.80 + 4.05 \times 0.700 + 0.500$

2

2

$= 75.13$

112.78

Continuation

28/10/21
7.22

Scanned by CamScanner