

Inspection Report for Flood Damage Work

Date

1 Name of PIUs

MV2 Post 7

2 Name of Block/Road

Gobarsahi Daman, path sir manali,
Ice Samur Se handhi Nagen

A For Road

1 Damage Location/Chainage

many location,

2 Damage Length

300m

3 Nature of Damage

pots/Seach due to flood/Heavy Ruins,

4 Details of Restoration Works

i Material being used in Restoration Works

Brick, Bats. - 459.90 m³

ii Equipments/Tools being used in Restoration Works

J.C.B, Roller, Tractor.

iii Procedure Taken up in Restoration Works

N/A

iv Restored Length

N/A

works found satisfactory.

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i Material being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored Length

N/A

Signature
Signature of JE/AE/EE

04.11.21
AE

24.11.21

Signature
कोयमालक अभियन्ता
(Name of Inspector)
ग्रामीण कार्य विभाग
कार्य प्रवर्धन, गहनार

YEAR (2021-2022)

GENERAL ABSTRACT OF COST

Restoration of Road from Babasahi Dumari Path Shiv mandir ke
Samane Se Gandhi Nagar in Mushari Block under F.D.R., RWD,
Works Division, Muzaffarpur East-1

Block :- Saraiya

District :- Muzaffarpur

| <u>Sl</u> <u>No.</u> | <u>Description</u> | <u>Amount</u> |
|-------------------------|-----------------------|-----------------|
| | Road Restoration Cost | Rs. 9,94,000.00 |

Total

9,94,000.00

Say Rs.

9,94,000.00

949491
Say Rs. 9.495 lacs

[Signature]
Junior Engineer
RWD, Works Section
Mushari

[Signature]
5.11.21
Assitant Engineer
RWD, Works Sub-Div.
Mushari

[Signature]
24.11.21
Executive Engineer
RWD, Works Division
Muzaffarpur East-1

As Per S.E. RWD (W) Circle Muz.
Letter No 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E. E. RWD. (W) Division Muzaffarpur

Technically Sanctioned for Rs. 9.495 lacs
(Rs. Nine lacs forty nine thousand five
hundred) only (provisionally)

[Signature]
27.12.21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur


Abstract of Cost & Detailed Estimate for


Restoration of Road from Babasahi Dumari Path Shiv mandir ke
Samane Se Gandhi Nagar in Mushari Block under F.D.R., RWD, Works
Division, Muzaffarpur East-1


| Sl. No. | SO R | Item of Work | Quantity | Unit | Rate | Amount |
|---------|----------|--|----------|----------------|-----------|-------------|
| 1 | | 2 | 6 | 7 | 8 | 9 |
| 1 | | Providing and laying Brick bats, including all taxes etc. all complete job as per specification and direction of E/I. | | | 2064.56 | 949491 |
| | | As per M.B | 459.90 | m ³ | 2161.18 | 993927.00 |
| 2 | 5.6. 2.4 | Labour for laying, fitting and fixing NP3 pipe with collors in line level and grade as well providing approved jointing materials and joints properly filled to make them water proof all complete as per specification and direction of E/I. (Hume pipe available within a lead of 40 mtr 1000 mm dia or 100 mm dia NP3 H.P | | | | |
| | | As per M.B | 0.00 | m | 3992.28 | 0.00 |
| | | | | | Total Rs. | 949491 |
| | | | | | | 9,93,927.00 |

Say Rs. 9,94,000.00

949491


Junior Engineer
RWD, Works Section
Musahari


Assitant Engineer
RWD, Works Sub-Div.
Musahari


Executive Engineer
RWD, Works Division
Muzaffarpur East-1