


(2)


**कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, गोगरी।**
E-mail ID.- eerwdgogri@gmail.com


संयुक्त निरीक्षण प्रतिवेदन


ग्रामीण कार्य विभाग, कार्य प्रमंडल, गोगरी अंतर्गत वर्ष 2021 के बाढ़/अतिवृष्टि से क्षतिग्रस्त पथों को मोटरेबुल करने के पश्चात् अद्योहस्ताक्षरी की उपस्थिति में संयुक्त रूप से कनीय अभियंता, सहायक अभियंता एवं अधीक्षण अभियंता, ग्रामीण कार्य विभाग, कार्य अंचल, सहरसा के पत्रांक 944 दिनांक 15.11.2021 के द्वारा किये गये मोटरेबुल पथ की जाँच हेतु प्रतिनियुक्त कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, गोगरी के साथ स्थल निरीक्षण किया गया जिसमें पथ में किये गये कार्य को प्राक्कलन के अनुरूप पाया गया। कार्य की वर्तमान स्थिति संतोषजनक एवं सभी पथ मोटरेबुल है।


क्र०	पथ का नाम	चैनेज कि०मी० में	क्षतिग्रस्त पथों की लम्बाई मी० में
1	2	3	4
1	NH-31 बजरंगवली स्थान देवठा से पैकान्त भाया नवटोलिया तक पथ का अस्थायी पुनर्स्थापन कार्य।	2.400 कि०मी० एवं 3.200 कि०मी०	32 मी०
2	कबेला ग्राम G.N बॉध महावीर स्थान होते हुए G.N बॉध से मुदारपुर गॉव तक पथ का अस्थायी पुनर्स्थापन कार्य।	0.650 कि०मी०	4.2 मी०
3	G.N बॉध माधवपुर से विश्नपुर तक पथ का अस्थायी पुनर्स्थापन कार्य।	0.00 से 1.700 किमी०	270 मी०
4	शिरोमणी ढाला से सतखुट्टी तक पथ का अस्थायी पुनर्स्थापन कार्य।	0.900 कि०मी० एवं 1.100 किमी०	148 मी०
5	G.N बॉध से इमादपुर तक पथ का अस्थायी पुनर्स्थापन कार्य।	0.070 किमी०	3 मी०
6	NH-31 सतीशनगर से कोरचक्का तक पथ का अस्थायी पुनर्स्थापन कार्य।	1.000 कि०मी०	100 मी०



कनीय अभियंता
गोगरी



कनीय अभियंता
चौथम


कनीय अभियंता
बेलदौर


कनीय अभियंता
परवत्ता


सहायक अभियंता
गोगरी/बेलदौर


सहायक अभियंता
चौथम/परवत्ता


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, गोगरी।


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, सहरसा।

Inspection Report for Flood Damage Work

Date :-

1. Name of Division :- RWD Works Division, Gogri

2. Name of Block/Road :- NAME OF ROAD :- Temporary Restoration work of G.N Bandh Madhopur to Bishnupur (Parbatta Block)

A. For Road

1. Damage Location/Chainage :- 1.700 KM

2. Damage Length :- 0.270 KM

3. Nature of Damage :- Heavy Rain/Flood

4. Details of Restoration Work :-

- Material being used in Restoration Work Brickbats
- Equipment/Tools being used in Restoration work :- Tractor, Trolley, Roller
- Procedure taken up in Restoration work :-
- Restored Length :- 0.270 KM

B. For Bridge

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage

4. Details of Restoration Work :-

- Material being used in Restoration Work :-
- Equipment/Tools being used in Restoration work :-
- Procedure taken up in Restoration work :-
- Restored Length :-

Signature of
J.E

Signature of
A.E

Signature of
E.E

Signature of
E.E RWD
W.D Saharsa

(5)

FDR
GENERAL ABSTRACT OF COST

Block:- PARBATTA

District:- KHAGARIA


Name of Work:-


Temporary Restoration Work of Parbatta Prakhanda Antargat
Madhaopur Panchayat Ke Gram Madhaopur GN Bandh Dhala Hote
Hue Vishnupur Gram Tak

SL. No.	Item of Work	Amount
1	TOTAL COST OF CONSTRUCTION	4.824 Lacs

3.665 Lacs


23.11.2021
Junior Engineer



Asstt. Engineer


Executive Engineer

SE
RWD

पत्रांक - 550310-4(550) बिबिध (कार्य) 23-29/11/2019-4849
दिनांक - 07/12/2021.

Technically sanctioned for Rs. ^{3.665} ~~4.824~~ Lacs (Rupees.
Three ^{Sixty six} ~~Four~~ lakh. ^{Five} ~~Eighty two~~ thousand ^{hundred} ~~four~~
Only.


Superintending Engineer
R.W.D. Works Circle
SAHARSA

19/04/22