

Restoration for the Matabele work in
Kradma Bazar St. Lekele; babatula in Matabele
Schedule XLV-Form No. 134

सर्वप्रकार का कागज
गुणवत्ता - १ दिवस
गुणवत्ता - १ दिवस

DIVISION

PERMANENT SUB-DIVISION
मार्क हा

MEASUREMENT BOOK

NO - 3831

Name to work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.

1

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Recorded measurement					
Named Work: - Restoration for					
metarabli in Kadha					
Bugar Se Khaki Baba					
to be via road n pur					
in Ganche Block					
L = 1.80 km wide					
R.D.R.					
Ass No					
Authority - E.E.R.W.D.W. Dir					
Chapter - 1					
Named Agency -					

Date of entry - 14/9/2021					
Work done					
(1) providing brick					
bats including					
spreading laying					
labour for -					
dry sand & stone					
do do as per					
2015					
- 1 x 4.95 x 2.35 x 0.30 = 3.49 M ³					
1 x 12.00 x 3.30 x 0.30 = 11.88 M ³					
2 x 7.80 x 2.20 x 0.22 = 7.55 M ³					
1 x 14.00 x 1.95 x 0.15 = 4.10 M ³					
3 x 9.90 x 2.65 x 0.22 = 17.32 M ³					
3 x 12.60 x 3.70 x 0.30 = 41.96 M ³					
1 x 21.00 x 3.20 x 0.80 = 20.16 M ³					
Continuation C.D. = 106.46 M ³					

