




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR

YEAR-2021-22



Name of the Road :-	Makari Tola SH-74 to Mushhar Tola Narayan Chowk Tak		
DISTRICT	Muzaffarpur		
DIVISION	Muzaffarpur West		
BLOCK	Sahebganj		
TOTAL LENGTH OF ROAD	:	1.190	KM
CONSTRUCTION COST	:	0.317	Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

0.304

प्रतिवेदन

कार्य का नाम:-

Makan' Tolash-74 to MusaharTola Narayanchar
Tare

.....पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में
यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड-

Bahabau

वित्तीय वर्ष -

प्राक्कलित राशि - Rs. 0.3175M

0.304

0.304

0.317

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 0.317 है, PRN
....., प्रखण्ड-Bahabau में यातायात बहाली हेतु आपातकालिन मरम्मत के
लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.21 द्वारा
दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू
करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी
घटनोत्तर स्वीकृति अपेक्षित है। MIS में प्रविष्टि कर दी गई है। MIS की यह सीमा है / MIS की SL No
20 पर है।

05/11/2021
कनीय अभियंता

05/11/21
सहायक अभियंता

05/11/21
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- E.E. RWD Prayagpur Woot

2 Name of Block/Road :- Makani tola SH-74 Musahani tola Hazayan chowk
taly

(A) For Road:

1. Damage Location/Chainage :-
2. Damage Length :- 02 M.
3. Nature of Damage :- due to flood & heavy rain.
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick Bat - 1.4 cum, Sand - 1.2 cum.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

The work is found satisfactory.

NA

Signature of JE/AE/EE
05/11/2021
AE

Signature
13.12.21

(Name of Inspection)

GENERAL ABSTRACT

Name of Road Makari Tola SH-74 to Mushhar Tola Narayan Chowk Tak
District Muzaffarpur
Block Sahebganj
Division Muzaffarpur West
Length of Road (in Km) 1.190 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	0.297 - 0.310
3	Sand Filling	0.007
4	Sand bag	0.000
5	H.P.	0.000
	SUB TOTAL	0.317
	GRAND SUB TOTAL	0.317

0.304 ✓
0.304

JE Sahb
RWD

AE
RWD

EE
RWD

As Per S.E. RWD (W) Circle Muz
Letter No 1170 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD. (W) Division Muzaffarpur

Technically Sanctioned for Rs. 0.304 lac
(Rs. Thirty thousand four hundred) only
(Provisionally)

28.12.21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur