

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- EE, RWD, Muzalpur Bara-1

2 Name of Block/Road :- Gaikhali / Kalyanpur chowk to Muzalpur chowk

(A) For Road:

1. Damage Location/Chainage :- At muddy location
2. Damage Length :- 81 mtr
3. Nature of Damage :- Road closed due to scouring of road shoulder & surface of river flood water
4. Details of Restoration Works :-
(i) Material being used in Restoration works:- Sand bag, N.C. Bamboo (235 mtr)
(ii) Equipment's/Tools being used in Restoration works:- JCB, tractor
(iii) Procedure taken up in Restoration works:- Dismantle restoration & traffic
(iv) Restored Length :- 81 mtr

(B) For Bridge:

The work found satisfactory

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
(i) Material being used in Restoration works:-
(ii) Equipment's/Tools being used in Restoration works:-
(iii) Procedure taken up in Restoration works:-
(iv) Restored Length :-


Signature of JE/AE/EE


Signature
06.12.21

(Name of Inspection)

GENERAL ABSTRACT

Name of Road Kalyanpur Chowk to Munni Chowk

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km)

0.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	0.000
3	Sand Filling	0.000
4	Sand bag	0.000
5	bamboo piles	36.17 40.196 = 41.37
6	Nylon thread	0.111 0.151 = 0.13
7	bamboo runners	4.535 ✓ 4.47
	SUB TOTAL	0.16 0.300 = 0.16
	GRAND SUB TOTAL	40.98 45.191 = 46.13 lacs



JE
RWD



AE
RWD



EE
RWD

Technically Sanctioned for Rs. 46.13 lacs
(Rs. Forty six lacs thirteen thousand) only
(provisionally)


26.2.22
अधिकारी अधियंता
ग्रामीण कार्य विभाग
कार्य अंचल, गुजफकरपुर