




# ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

## DETAILED PROJECT REPORT FOR FDR

YEAR-2021-22



Name of the Road :- Panchrukhiya Dhala to Tulsi Chowk Hote Huye To Hussepur Siwan Mushari Pull SH Road Tak

DISTRICT Muzaffarpur

DIVISION Muzaffarpur West

BLOCK Sahebganj

TOTAL LENGTH OF ROAD : 4.220 KM

CONSTRUCTION COST : ~~16.403~~ 15.43627 Lac

Submitted By :-  
Executive Engineer  
RWD Work Division, Muzaffarpur West

15.436

## प्रतिवेदन

कार्य का नाम:- पुनर्निर्माण काम - ले नुलहा - लोक बोर्डर एन  
पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में  
यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- सिद्धार्थ  
वित्तीय वर्ष - 2021-22  
प्राक्कलित राशि - Rs. 12.755 **15.436**

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 12.755 **15.436** है,  
प्रखण्ड- सिद्धार्थ में यातायात बहाली हेतु आपातकालीन मरम्मत के  
लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.21 द्वारा  
दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू  
करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी  
घटनोत्तर स्वीकृति अपेक्षित है। पथ मरम्मत के लिए प्रस्तावित राशि 12.755 के अतिरिक्त

S. S. Singh  
कनीय अभियंता

S. S. Singh  
सहायक अभियंता

K. S. Singh  
कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल:-

## Inspection Report for Flood Damage Work

Date:- 2/12/2021

1 Name of PIUs :- E.E.R.W.D. WORKS DIVISION Muzir West.

2 Name of Block/Road :- Sahobganj

### (A) For Road:

1. Damage Location/Chainage :-

2. Damage Length :- 80m

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:

(iv) Restored Length :- 80 m

Brick Bag = 532.60  
sand bag = 11224.80  
The work completed for road & safety.

### (B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

H.D.

Signature of JE/AE/EE

Signature  
02-12-21

(Name of Inspection)

## GENERAL ABSTRACT

Name of Road Panchrukhiya Dhala to Tulsi Chowk Hote Huye To Hussepur Siwan Mushari Pull SH Road Tak  
District Muzaffarpur  
Block Sahebganj  
Division Muzaffarpur West  
Length of Road (in Km) 4.220 Km

| Sl. No. | DESCRIPTION     | AMOUNT (LAKHS)           |
|---------|-----------------|--------------------------|
| 1       | Earthwork       | 0.000                    |
| 2       | Brick Bats      | 10.998 <del>12.091</del> |
| 3       | Sand Filling    | 0.000                    |
| 4       | Sand bag        | 4.438 4.312              |
| 5       | H.P.            | 0.000                    |
|         | SUB TOTAL       | 16.403                   |
|         | GRAND SUB TOTAL | 16.403                   |


~~15,43,627 =~~  
15.436

  
JE

RWD

  
AE


RWD

  
EE

RWD

As Per S.E. RWD (M) Circle Muz  
Letter No 1179 Dated 01/10/2021  
Estimate has been verified by inspecting  
E.E. RWD. (M) Division

Technically Sanctioned for Rs. 15.436 Lacs  
(Rs. Fifteen Lacs forty three thousand six  
hundred) only (provisionally)

  
28.2.22  
Superintending Engineer  
Rural Works Department  
Work Circle, Muzaffarpur