

પ્રજ્ઞા - જાલીચંદ્ર

Measurement Book

Lalan Das Kp Desai to
Bangspatti to Medhu -
Sahni path.

M. B. No. 252

Name of work - ¹Temporary Restoration of
 Situation of work - Flood Damage Road
 Agency by which work is executed -
 Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of scheme :-	Lahan Des be Dera				
	to Banaspatti to Medhul				
	Sahni Path.				
Name of Circle :-	R.W.D Works Circle				
	Singamrhi				
Name of Division :-	R.W.D Works Division,				
	Belsand				
Authority :-	E.C. R.W.D. Belsand				
Date of Entry.	30.10.2021				

Work done

① Providing and laying ditches					
filled by Buck Bats &					
Rubbish					
SP ⁿ					
4.200x4.200x0.300 = 5.355m ³					
4.200x3.900x0.950 = 15.561m ³					
20.916 m ³					
① Buck Bats 80% of Qty					
vide Table Page no ① = 16.732m ³					
② Rubbish 20% of Qty					
vide Table Page no ① = 4.184m ³					
③ Providing and laying					
Rock Pile dia. 300 mm					
SP ⁿ					
2x2.500 = 5.000m					

Vishal
 30/10/2021

ABSTRACT OF COST

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① P/L of brick bat					
obtained from					
Chimney —					
Qty. vide TMB P①					
Item no. (i) (i) = 16.732 m ²					
@ Rs 1827.73/m ²					Rs 30581 = 00
2) P/L quarry material					
rubbish for filling —					
Qty. vide TMB P①					
Item no. (i) (i) = 4.184 m ²					
@ Rs 873 = 00/m ²					Rs 3652 = 00
3) P/L R.C.C. pipe					
dia 300mm —					
Qty. vide TMB P①					
Item no. (2) = 5.00m					

@ Rs 502.61/m

Rs 2513 = 00

Rs 36746 = 00

Yashraj
3.11.24
EE

Sagunib
3.11.2022
S.E