

ਮਲਕ-ਕਲੀਓਰ
Measurement Book
Balug pmbay se Muslim
toq.

M.B. No. 265

Name of work - Temporary Restoration
 Situation of work - of Flood Damaged
 Agency by which work is executed -
 Date of measurement -
 No. and date of agreement
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Scheme: <u>Bakra Pkhsy</u>					
<u>for Muslim Pkhsy</u>					
Name of Circle: <u>R.W.D. Works</u>					
<u>Circle Sidamahi</u>					
Name of Division: <u>R.W.D.</u>					
<u>Works Division Belson</u>					
Authority: <u>EE R.W.D.</u>					
<u>Belson</u>					
Date of Entry: <u>30/10/2021</u>					

Work done					
① Providing and laying of filter ditches by					
Brick Batts & Rubbish					
5.00 x 3.800 x 0.900 = 17.100m ³					
2.900 x 3.800 x 0.600 = 6.612m ³					
3.00 x 2.00 x 0.450 = 2.700m ³					
26.412m ³					
① Bricks Batts - 80% of					
Qty vide TMS Item no ①					
21.120m ³					
① Rubbish - 20% of					
Qty vide TMS Item no ①					
5.289m ³					
Village 2021					
no continuation					

Mohd
30.10.2021

3

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① P/L of brickbat obtained from chimney -- Qty. vide TMBP ① Item no - (I)(C) = 21.29m ²					
@ Rs 1827.73/m ²					Rs 38618 = 0
2) P/L quarry material rubbish for filling voids -- do -- E/I Qty. vide TMBP ② Item no: - (I)(II) = 5.283m ²					
@ Rs 73 = 00/m ²					Rs 4612 = 0
					43230 = 0
(Rupees)					Saguis

3-11-21
20

3.11.2022
J.E