

Schedule XLV-Form No. 134

BAGAWA-I

DIVISION

SUB-DIVISION

Black

MEASUREMENT BOOK

1329

प्रमाणित किया जाता है कि इस मापीयुक्त न
परीन द्वारा टंकित क्र० सं०-०१ से १००५०
है। यह मापीयुक्त नक्काशक अभियन्ता,
मापीय कार्य विभाग, कार्य अवर, प्रमंडल

अ००६१-१

(Signature)
26/6/21
कार्यपालक अभियन्ता
मापीय कार्य विभाग
केंद्र प्रमंडल, बंगला-१
26/6/21

Reissued to the Survey
Chub.

(Signature)
26/6

Schedule PLV-Form No. 134

DIVISION

SUB-DIVISION

Measurement Book

No. _____

Name of Officer _____


Date of first entry _____

Date of last entry _____

Name of work -
 Situation of work -
 Agency by which work is executed -
 Date of measurement -
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Repair of Road breaches (Damaged by Flood) for motorability in Makari Bazar to Tiwan Tola					
P.Y.	2021-22				
Work Head - PDR					

Measurement					
(1/2) Plv material and Labour for laying brick bat - T/S					
1	X	5.85	X	3.60	X 0.45 = 9.48 m ³
1	X	30.10	X	3.40	X 0.38 = 38.76 m ³
1	X	15.50	X	3.80	X 0.84 = 45.57 m ³
1	X	4.10	X	3.54	X 0.62 = 9.10 m ³
2	X	30.10	X	3.56	X 0.53 = 113.21 m ³
1	X	22.50	X	3.87	X 0.52 = 45.28 m ³
					313.29 m ³
					
J.E. 09/10/2021					
Continuation					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
③ Plr Material and labours for laying brick bats - 7/5					
313.29 m ³ vide Page ①					
Rs 2048 = 30/m ³					Rs 641712 = w
					Rs 641712 = w
Add 12% G.S.T					Rs 77005 = w
Add 1% L.Cess					Rs 6417 = w
Add 8% P					Rs 10894 = w
					Rs 736028 = w
Subtotal 5-11-707 5.8					

C/P

~~Rs 736028~~
25/11/70
E E