

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मधुबनी।

पत्रांक:- 924 अड०

दिनांक:- 23/4/2022

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मधुबनी।

सेवा में,

नोडल पदाधिकारी,
एम0आर0 3054
अनुरक्षण एवं मरम्मत कोषांग,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:- शीर्ष 3054 अंतर्गत बिहार ग्रामीण पथ अनुरक्षण नीति-2018 के तहत स्वीकृत कार्यों के आवंटन की मांग हेतु अध्याचना के संबंध में।

प्रसंग:- भवदीय पत्रांक 113 अनु0 पटना दिनांक 10.01.2020

महाशय,

उपरोक्त विषयक प्रासंगिक पत्र के अनुपालन में शीर्ष 3054 अंतर्गत बिहार ग्रामीण पथ अनुरक्षण नीति-2018 से संबंधित पथ में आवंटन की मांग की गयी है। वांछित विवरणी विहित प्रपत्र में तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

अतः श्रीमान् से अनुरोध है कि उक्त पथ में आवंटन उपलब्ध कराने की कृपा की जाय ताकि स-समय भुगतान किया जा सके।
अनु- यथोक्त।

विश्वासभाजन

कार्यपालक अभियंता

ग्रा0का0वि0, कार्य प्रमंडल, मधुबनी

22.4.2022

22.4.2022

New Maintenance Policy-2018
FORM GFR 19-A
(See Government of India's decision (1) below Rule-150)
Form of Utilization Certificate upto 22-April-2022

SL NO	Name of Scheme	Sanction No & date with Amount (in lacs)	Amount Received (in Lacs)	Particulars
1.	Construction of Rural roads under New Maintenance Policy-2018	Fund Received from Secretary Cum Empowered officer BRRDA Patna upto F/Y -2022-23		Certified that out of Rs. 1636.63573 lacs. of grants-in-aid sanctioned upto the year 2022-23 (22.04.2022) in favour of Executive Engineer R.W.D (Works) Division Madhubani under this department, a sum of Rs. 1631.07627 lacs. has been utilized for the purpose of New Maintenance Policy-2018 schemes Fund and Rs. 5.55946 lacs. remaining unutilized at the end of the period under report.
		Total:-	<u>1636.63573</u>	
		Expenditure the F/Y - 2022-23	<u>1631.07627</u>	
		Balance-	5.55946	


2. Certified that I have satisfied myself that the condition on which the grant in aid was sanctioned have been duly fulfilled/are being fulfilled and then I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised: -

- (i) Works have been supervised by Executive Engineer /Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- (iii) Construction material have been tested.
- (iv) Measurements have been recorded in the MBS and Test check conducted by the Assistant Engineer/ Executive Engineer
- (v) All other codal formalities have been observed.

3. **Physical Progress achieved:-**

- (vi) Construction of Road Works.
- (vii) Construction of CD Works.


Sr. Divisional Account Officer
R.W.D Works Division Madhubani


Executive Engineer
R.W.D Works Division Madhubani
22.4.22

RWD, Works Division, Madhubani
Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:-RWD, (W) Division, Madhubani																		
Sl No	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakhs)	Up-to-date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	amount (in Lakh)	Initial Rectification With Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/MA/MAD /20/0004	LO31- BIKAMPURBAILA	NEA22000481	1863 & 24-06-2019	6.500	212.03080	127.07200	52.02206	167580/2020-21 & 05-03-2021	04-12-2021	On-going	2882	25MM	5.20	0.00000	0.00000	94.56169	

नोट:-
विभागीय पत्रांक-3054(र) 3054-4-04/2020 पार्त 4 5047 दिनांक 23.12.2021 के आलेख में प्रमाणित किया जाता है कि-
1. गुणवत्ता पूर्ण एवं विशिष्टियों के अनुसार कार्य कराने के बाद NIB में दर्ज किया गया है।
2. सम्बंधित कार्य कर्तव्य अभियंता द्वारा कराया गया (100% जांचा गया) सहितक अभियंता द्वारा 50% तथा कार्यपालक अभियंता द्वारा 10% जांचा गया तथा MIS पर Updated किया गया।

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्रमाणित
22.4.22

Name of work : LO31 - BIKAMPURBALIA

Name of customer : Nirmal Kumar Prasad

(R)Rural Road

Good

Average

Poor

< 4000

4001 - 5000

> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMF(cm)	Speed(Km/Hr)	Ull(m/m/Km)	Corrected Ull (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction	Remarks
06/04/22	18:37:56	27	100	100	28.0 cm	30.0 Km/Hr	2800.0 mm/Km	2792	3.78	Good	26.2393753	N	86.1064157	E	Normal
06/04/22	19:35:10	27	100	200	21.0 cm	9.6 Km/Hr	2100.0 mm/Km	2143	2.98	Good	26.2394094	N	86.0965501	E	Normal
06/04/22	19:35:23	27	100	300	33.0 cm	25.9 Km/Hr	3300.0 mm/Km	3255	4.33	Good	26.2387495	N	86.0965052	E	Normal
06/04/22	19:35:39	27	100	400	26.0 cm	23.4 Km/Hr	2600.0 mm/Km	2607	3.55	Good	26.2376890	N	86.0965357	E	Normal
06/04/22	19:35:52	27	100	500	28.0 cm	27.0 Km/Hr	2800.0 mm/Km	2792	3.78	Good	26.2372160	N	86.0974817	E	Normal
06/04/22	19:36:08	27	100	600	34.0 cm	22.5 Km/Hr	3400.0 mm/Km	3348	4.44	Good	26.2368460	N	86.0981455	E	Normal
06/04/22	19:36:25	27	100	700	33.0 cm	22.4 Km/Hr	3300.0 mm/Km	3255	4.33	Good	26.2358160	N	86.0985890	E	Normal
06/04/22	19:36:43	27	100	800	27.0 cm	19.2 Km/Hr	2700.0 mm/Km	2699	3.67	Good	26.2356070	N	86.0934501	E	Normal
06/04/22	19:37:01	27	100	900	27.0 cm	20.8 Km/Hr	2700.0 mm/Km	2699	3.67	Good	26.2352133	N	86.1005564	E	Normal
06/04/22	19:37:18	27	100	1000	22.0 cm	21.1 Km/Hr	2200.0 mm/Km	2236	3.1	Good	26.2345476	N	86.1008768	E	Normal
06/04/22	19:37:31	27	100	1100	24.0 cm	26.2 Km/Hr	2400.0 mm/Km	2421	3.33	Good	26.2345476	N	86.1008768	E	Normal
06/04/22	19:37:44	27	100	1200	29.0 cm	29.1 Km/Hr	2900.0 mm/Km	2885	3.89	Good	26.2345476	N	86.1008768	E	Normal
06/04/22	19:37:57	27	100	1300	33.0 cm	27.2 Km/Hr	3300.0 mm/Km	3255	4.33	Good	26.2345476	N	86.1008768	E	Normal
06/04/22	19:38:10	27	100	1400	33.0 cm	27.0 Km/Hr	3300.0 mm/Km	3255	4.33	Good	26.2345476	N	86.1008768	E	Normal
06/04/22	19:38:23	27	100	1500	31.0 cm	28.0 Km/Hr	3100.0 mm/Km	3070	4.11	Good	26.2345476	N	86.1008768	E	Normal
06/04/22	19:38:39	27	100	1600	29.0 cm	23.1 Km/Hr	2900.0 mm/Km	2885	3.89	Good	26.2345476	N	86.1008768	E	Normal
06/04/22	19:39:07	27	100	1700	29.0 cm	12.6 Km/Hr	2900.0 mm/Km	2885	3.89	Good	26.2345476	N	86.1008768	E	Normal
06/04/22	19:39:30	27	100	1800	29.0 cm	15.5 Km/Hr	2900.0 mm/Km	2885	3.89	Good	26.2289468	N	86.1008310	E	Normal
06/04/22	19:39:44	27	100	1900	30.0 cm	24.9 Km/Hr	3000.0 mm/Km	2977	4	Good	26.2281648	N	86.1007853	E	Normal
06/04/22	19:39:57	27	100	2000	33.0 cm	26.7 Km/Hr	3300.0 mm/Km	3255	4.33	Good	26.2261648	N	86.1007853	E	Normal
06/04/22	19:40:13	27	100	2100	28.0 cm	23.9 Km/Hr	2800.0 mm/Km	2792	3.78	Good	26.2243299	N	86.1003122	E	Normal

Mohit
6.4.22

Mohit
6.4.22

Mohit
6.4.22

Mohit
6.4.22

Name of work : LO31 - BIKAMPURBALIA

Name of customer : Nimal Kumar Prasad

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

06/04/22	19:40:35	27	100	2200	26.0 cm	16.5 Km/Hr	2600.0 mm/Km	2607	3.55	Good	26.2233400	N	86.1001291	E	Normal
06/04/22	19:40:50	27	100	2300	27.0 cm	24.9 Km/Hr	2700.0 mm/Km	2639	3.67	Good	26.2229452	N	86.1000299	E	Normal
06/04/22	19:41:06	27	100	2400	33.0 cm	22.2 Km/Hr	3300.0 mm/Km	3255	4.33	Good	26.2220259	N	86.1004419	E	Normal
06/04/22	19:41:19	27	100	2500	31.0 cm	26.4 Km/Hr	3100.0 mm/Km	3070	4.11	Good	26.2209921	N	86.1008310	E	Normal
06/04/22	19:41:41	27	100	2600	21.0 cm	16.8 Km/Hr	2100.0 mm/Km	2143	2.98	Good	26.2202406	N	86.1010294	E	Normal
06/04/22	19:42:07	27	100	2700	34.0 cm	13.9 Km/Hr	3400.0 mm/Km	3348	4.44	Good	26.2191992	N	86.1010065	E	Normal
06/04/22	19:42:23	27	100	2800	26.0 cm	21.8 Km/Hr	2800.0 mm/Km	2607	3.55	Good	26.2183485	N	86.1010752	E	Normal
06/04/22	19:44:33	27	100	2900	30.0 cm	14.4 Km/Hr	3000.0 mm/Km	2977	4	Good	26.2174082	N	86.1012735	E	Normal

Mark
6.4.22

6/4/22

6/4/22

6/4/22

4360

Name of Customer: Nirmal Kumar Prasad, Machine no: 19195, Road: LO31 - BIKAMPURBALA, Date: 06-04-22, Section No: 27, Equation: $Y = 0.927 X + 196.3$

UIV mm/km

2950

1600

0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 0.8 0.9 1 1.1 1.2 1.3 1.4 1.5 1.6 1.7 1.8 1.9 2 2.1 2.2 2.3 2.4 2.5 2.6 2.7 2.8 2.9 3

Distance*1000 m

Nirmal
6.4.22Nirmal
6/4/22Nirmal
6/4/22Nirmal
06/04/22
ETC

Name of work		: LO31 - BIKAMPURBALIA													
Name of customer		: Nirmal Kumar Prasad													
(R)Rural Road															
Good				Average				Poor							
< 4000				4001 - 5000				> 5000							

Date	Time	Test No	Distance(m)	Total Distance(m)	BUM(µm/cm)	Speed(km/hr)	U(µm/km)	Corrected UI (mm/km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
06/04/22	19:44:40	28	100	100	30.0 cm	14.4 Km/hr	3000.0 mm/km	2977	4	Good	26.2174082	N	86.1012735	E	Normal
06/04/22	19:44:52	28	100	200	34.0 cm	29.8 Km/hr	3400.0 mm/km	3348	4.44	Good	26.2174082	N	86.1012735	E	Normal
06/04/22	19:45:19	28	100	300	27.0 cm	13.7 Km/hr	2700.0 mm/km	2699	3.67	Good	26.2136888	N	86.0999002	E	Normal
06/04/22	19:45:34	28	100	400	28.0 cm	22.6 Km/hr	2800.0 mm/km	2792	3.78	Good	26.2128057	N	86.0999689	E	Normal
06/04/22	19:45:46	28	100	500	28.0 cm	30.3 Km/hr	2800.0 mm/km	2792	3.78	Good	26.2121592	N	86.0999536	E	Normal
06/04/22	19:46:06	28	100	600	33.0 cm	18.9 Km/hr	3300.0 mm/km	3255	4.33	Good	26.2112036	N	86.0999536	E	Normal
06/04/22	19:46:26	28	100	700	34.0 cm	17.6 Km/hr	3400.0 mm/km	3348	4.44	Good	26.2101240	N	86.0993357	E	Normal
06/04/22	19:46:46	28	100	800	33.0 cm	19.6 Km/hr	3300.0 mm/km	3255	4.33	Good	26.2102671	N	86.0985041	E	Normal
06/04/22	19:47:07	28	100	900	30.0 cm	15.7 Km/hr	3000.0 mm/km	2977	4	Good	26.2104425	N	86.0981607	E	Normal
06/04/22	19:47:27	28	100	1000	28.0 cm	19.0 Km/hr	2800.0 mm/km	2792	3.79	Good	26.2095060	N	86.0975580	E	Normal
06/04/22	19:47:42	28	100	1100	28.0 cm	22.2 Km/hr	2800.0 mm/km	2792	3.78	Good	26.2088099	N	86.0978174	E	Normal
06/04/22	19:48:05	28	100	1200	27.0 cm	16.6 Km/hr	2700.0 mm/km	2699	3.67	Good	26.2077570	N	86.0973978	E	Normal
06/04/22	19:48:43	28	100	1300	31.0 cm	9.1 Km/hr	3100.0 mm/km	3070	4.11	Good	26.2073660	N	86.0973673	E	Normal
06/04/22	19:48:58	28	100	1400	33.0 cm	24.1 Km/hr	3300.0 mm/km	3255	4.33	Good	26.2073660	N	86.0973673	E	Normal
06/04/22	19:49:12	28	100	1500	30.0 cm	25.7 Km/hr	3000.0 mm/km	2977	4	Good	26.2053480	N	86.0983057	E	Normal
06/04/22	19:49:24	28	100	1600	30.0 cm	28.2 Km/hr	3000.0 mm/km	2977	4	Good	26.2047453	N	86.0988779	E	Normal
06/04/22	19:49:37	28	100	1700	33.0 cm	28.5 Km/hr	3300.0 mm/km	3255	4.33	Good	26.2038145	N	86.0988779	E	Normal
06/04/22	19:49:50	28	100	1800	34.0 cm	28.5 Km/hr	3400.0 mm/km	3348	4.44	Good	26.2033911	N	86.0988626	E	Normal
06/04/22	19:50:03	28	100	1900	19.0 cm	27.7 Km/hr	1900.0 mm/km	1958	2.75	Good	26.2033911	N	86.0988626	E	Normal
06/04/22	19:50:29	28	100	2000	32.0 cm	13.7 Km/hr	3200.0 mm/km	3163	4.22	Good	26.2015791	N	86.1001444	E	Normal
06/04/22	19:50:45	28	100	2100	31.0 cm	21.8 Km/hr	3100.0 mm/km	3070	4.11	Good	26.2015562	N	86.1013193	E	Normal

HAB
6/4/22

6/4/22

6/4/22

6/4/22

Name of work		: LO31 - BIKAMPURBALA													
Name of customer		: Nirmal Kumar Prasad													
(R/Rural Road															
Good				Average				Poor							
< 4000				4001 - 5000				> 5000							
06/04/22	19:51:01	28	100	2200	25.0 cm	23.6 Km/Hr	2500.0 mm/Km	2514	3.44	Good	26.2015352	N	86.1018534	E	Normal
06/04/22	19:51:23	28	100	2300	21.0 cm	15.8 Km/Hr	2100.0 mm/Km	2143	2.98	Good	26.2014055	N	86.1031427	E	Normal
06/04/22	19:51:48	28	100	2400	31.0 cm	14.7 Km/Hr	3100.0 mm/Km	3070	4.11	Good	26.2011938	N	86.1043634	E	Normal
06/04/22	19:52:07	28	100	2500	25.0 cm	18.5 Km/Hr	2500.0 mm/Km	2514	3.44	Good	26.2011938	N	86.1043634	E	Normal
06/04/22	19:52:37	28	100	2600	30.0 cm	11.8 Km/Hr	3000.0 mm/Km	2977	4	Good	26.2024221	N	86.1055536	E	Normal
06/04/22	19:53:00	28	100	2700	21.0 cm	14.8 Km/Hr	2100.0 mm/Km	2143	2.98	Good	26.2026453	N	86.1053553	E	Normal
06/04/22	19:53:17	28	100	2800	25.0 cm	22.2 Km/Hr	2500.0 mm/Km	2514	3.44	Good	26.2026453	N	86.1053553	E	Normal
06/04/22	19:53:43	28	100	2900	29.0 cm	13.8 Km/Hr	2900.0 mm/Km	2885	3.89	Good	26.2026453	N	86.1053553	E	Normal
06/04/22	19:53:58	28	100	3000	29.0 cm	23.1 Km/Hr	2900.0 mm/Km	2885	3.89	Good	26.2026453	N	86.1053553	E	Normal
06/04/22	19:54:12	28	100	3100	26.0 cm	26.7 Km/Hr	2600.0 mm/Km	2607	3.55	Good	26.2026453	N	86.1053553	E	Normal
06/04/22	19:54:28	28	100	3200	30.0 cm	22.2 Km/Hr	3000.0 mm/Km	2977	4	Good	26.2026453	N	86.1053553	E	Normal
06/04/22	19:55:11	28	100	3300	31.0 cm	22.2 Km/Hr	3100.0 mm/Km	3070	4.11	Good	26.2026453	N	86.1053553	E	Normal
06/04/22	19:55:41	28	100	3400	34.0 cm	23.2 Km/Hr	3400.0 mm/Km	3348	4.41	Good	26.2037564	N	86.1064664	E	Normal

NAID
2.4.22

6/14/22
6/14/22

6/14/22
6/14/22

6/14/22
6/14/22

4300


Name of Customer: Nirmal Kumar Prasad, Machine no: 19195, Road: LO31 - BIKANIPURBALIA, Date: 06-04-22, Section No: 23, Equation: $Y = 0.927 X + 196.3$

UV mm/km
2900

1500

0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 0.8 0.9 1 1.1 1.2 1.3 1.4 1.5 1.6 1.7 1.8 1.9 2 2.1 2.2 2.3 2.4 2.5 2.6 2.7 2.8 2.9 3 3.1 3.2 3.3 3.4 3.5

Distance*1000 m



N 48/23
6.4.22

SMM
10/04/22

6/4/22
AC

06/04/22
EC