

Schedule XLV-Form No. 134

BALDWIN I DIVISION


2714-2 SUB-DIVISION

MEASUREMENT BOOK

1345

प्रमाणित किया जाता है कि इस मापीपुस्त में
मशीन द्वारा टेकिट क्र० सं०-११ से १००५०
पुर्न है। यह मापीपुस्त यह अभियन्ता
आसीन कार्य दिभाग में प्रमंडल

..... २०/६/१२


कार्यपालक अभियन्ता
सामान्य कार्य दिभाग
कमि प्रमंडल, बगहा-१
26/6/12

26/6/12 10 56 Santosh
Chaudhary.


26/6/12

Schedule PLV-Form No. 134

BAGHA-T DIVISION
BAGHA-T SUB-DIVISION

Measurement Book

No. 1345

Name of Officer _____
Date of first entry _____
Date of last entry _____

No. and date of agreement.
(These four lines should be repeated at
the commencement of the measurements relating
to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Repair of Road breaches (Damaged by Flood) for motorability in Town to Triphuni					
F.Y - 2021-22					
Work Head - P.D.R					

	Measurement	
($\frac{7}{4}$) Piv fitter and Labour for cutting Bamboo Piles — JTS —	256.0 m	
($\frac{4}{5}$) Piv and Labour for fitting and stringing bamboo runner — JTS —	272.0 m	
Continuation		

