

प्र० - राजीवगुप्ता

**Measurement Book**

Balua - phulwariq .

---

M.R.No. 253

---

Name of work - Temporary restoration of  
 Situation of work - flood Damage Rec  
 Agency by which work is executed -  
 Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Scheme :-	Balkan	for Phulwanya			
Name of Circle & R.W.D Work division					
	Circles sitamarkh				
Name of Division :- R.W.D Work division,					
	Belsands				
Authority :-	E.E	R.W.D	Belsand		
Date of Entry :-	30/10/2021				

### Work done

$29.00 \times 3.70 \times 1.250 = 135.937 m^3$
$3.00 \times 2.00 \times 0.900 = 5.400 m^3$
$2.00 \times 1.00 \times 0.750 = 1.500 m^3$
$4.500 \times 1.500 \times 0.750 = 5.062 m^3$
$4.00 \times 1.00 \times 0.600 = 2.400 m^3$
$7.500 \times 3.70 \times 0.750 = 210.93 m^3$
$3.00 \times 2.00 \times 1.00 = 6.000 m^3$
$2.00 \times 0.900 \times 0.900 = 1.620 m^3$
$179.024 m^3$
(i) Bricks Bats - 80% of Opendis
vide item no. (i) - $143.219 m^3$
(ii) Rubbishes - 20% of Ofs
vide item no. (i) - $35.805 m^3$
Vide sum
30/10/2021
OB

Continuation

Mudhra  
30/10/2021  
E.C

## ABSTRACT OF COST

3

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① P/L of brick bat obtained from chimney - - do - -					
Qty. vide TMS P(1)					
Item no:- (1)(ii) = 142.219m <sup>3</sup>					
@ Rs 182/- /m <sup>3</sup>	Rs 261765 = 00				
2) P/L quarry material rabbit for filling --					
Qty. vide TMS P(1)					
Item no:- (1)(ii) = 35.805m <sup>3</sup>					
@ Rs 873/m <sup>3</sup>	Rs 31257 = 00				
(Kishore Sajwan)					