

Measurements should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Record against</u>					
N/A - Temporary restoration of Permanent Pan dahan + 2 Karamuli work					
N/A - Departmental					
Date of work					01.11.2024

① Bridge layering in ditches with base back incl. down slip, unloading & right turning all comp. jobs.					
Est. on					
12.00 m	x	2.00	+ 3.00		
			<u>2</u>		
			x 1.50 + 1.80 + 1.20		45.00 m
			<u>3</u>		
13.00	x	0.60	+ 1.60		
			<u>2</u>		
			x 0.90 + 1.00 + 1.60		17.28 m
			<u>3</u>		
200	x	1.00	+ 1.50		
			<u>2</u>		
			1.20 + 0.90 + 1.00		11.20 m

Continuation

CU - 74.13 m

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Abstract of work				
N/A - Temporary reconstruction of Barricade for duty to Barricade raised					
N/A - Departmental					
Date of work					01.11.2024
① Filling & laying in trenches with brick bats					

V.10013 P(2)	285.58 m			
	@ 2001.96/m	532487.2		
② Supply of bamboo 6 m to 8 m				
V.10013 P(2)	47 m			
	@ 166.50/pan	7826.0		
③ Labour for cutting 62 m to 75 m long bamboo				
V.10013 P(3)	37 m			
	@ 31.20	1154.4		
	C. & D.	5,41,452.0		

Continuation

Scanned with CamScanner