

FDR (જોડ)

# Schedule XLV-Form No. 134

લોહી દોહવા રાત્રીએ બાપર દિવાળી કે ગુરૂદેવ  
તો સારી રીતે હર પકાણી સિવાજ નહીં ।

Buxar

DIVISION

Simeri

SUB-DIVISION

MEASUREMENT BOOK

1606

पुनर्निर्माण कार्य के लिए अग्रिम  
प्लान का अंश प्रमाणित - 100 (एक सौ)  
पुनर्निर्माण के लिए प्रमाणित है,  
संलग्न अभिलेख, माफिया एवं भवन -  
वर्ग 3.4.2. प्रवेश (माल) के माफिया  
प्रदान करने वाले हैं।

<sup>28-09-2017</sup>  
Executive Engineer  
R.W.D. (W.) Div., Buxar

<sup>28-09-2017</sup>  
E.E.

Sch. XLV - Form No. 134

Buxar DIVISION  
Simri SUB-DIVISION

## Measurement Book

No. 1606  
लोह्य निवासी कृष्ण चन्द्र मिश्र  
से प्रदान-7012 45716) नं

Name of Officer Shiv Kumar Mishra

A.E. Simri

Date of first entry \_\_\_\_\_

Date of last entry \_\_\_\_\_

Name of Work—  
 Situation of Work—  
 Agency by which work is executed—  
 Date of Measurement—  
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

| Particulars    | Details of actual measurement |    |    |    | Contents of area |
|----------------|-------------------------------|----|----|----|------------------|
|                | No.                           | L. | B. | D. |                  |
|                | <u>1st on A/c Bill.</u>       |    |    |    |                  |
| Name of work:  | → Restoration of              |    |    |    |                  |
|                | the road from LOU chhotka     |    |    |    |                  |
|                | Rajpur Bagar Siwala to        |    |    |    |                  |
|                | Pasnaki Siwan via Gurudev     |    |    |    |                  |
|                | Nages.                        |    |    |    |                  |
| Agency:        | → Sanjay Kumar                |    |    |    |                  |
|                | vill-Pawar, Bhojpur.          |    |    |    |                  |
| Agg. no.:      | → 18 F2/2021-22               |    |    |    |                  |
| Date of start: | → 19.08.21                    |    |    |    |                  |

| Record Entry.                     |    |      |      |                       |  |
|-----------------------------------|----|------|------|-----------------------|--|
| Pot Measurement.                  |    |      |      |                       |  |
| 1.) Emergent repairs by billing   |    |      |      |                       |  |
| Bricks Bats in flood damaged      |    |      |      |                       |  |
| stretch of the road for making    |    |      |      |                       |  |
| it Motorable -- as per s/o of E/E |    |      |      |                       |  |
| No.                               | L. | B.   | D.   | Qty (M <sup>3</sup> ) |  |
| 1                                 | 30 | 1.12 | 0.51 | 17.14 M <sup>3</sup>  |  |
| 1                                 | 30 | 1.12 | 0.60 | 20.16 "               |  |
| 1                                 | 30 | 0.91 | 1.21 | 33.03 "               |  |
| 1                                 | 5  | 1.07 | 1.37 | 7.33 "                |  |
| 1                                 | 15 | 0.71 | 0.81 | 8.63 "                |  |
| 1                                 | 30 | 1.12 | 1.00 | 33.60 "               |  |
|                                   |    |      |      | 119.89 M <sup>3</sup> |  |

10/09/21  
 J.E.  
 10/09/21  
 Continuation  
 EE

Continuation