

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road: - Temporary					
Restoration of Road					
From Begda passy path					
To Kamalpur					
Agency: -					
Head: F.D.R					
Actual length of Road - 1.831 km					
Flood affected Road length - 0.136 km					

Record entry					
(1)	Sand filling in				
	foundations Trenches				
	as per drawing				
	2 X 25 X 1.50 X 0.90				82.500 m ³
	1 X 15 X 2.25 X 0.90				42.188 m ³
	1 X 16.00 X 3.50 X 0.90				31.500 m ³
	2 X 25 X 1.40 X 0.90				105.00
					185.00
					261.188

Continuation

14) Supply of
Bamboo at Site - 109.

~~48~~
~~22/11/2021~~
~~86~~

~~48~~
~~22/11/2021~~
~~012~~

Scanned with CamScanner

ABSTRACT COST

9

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
(1)		Sand Filling in			
		foundations d/c			
		At 4 vide Tmp (p) 6			
		261.155 m ³ @ 582.71/m ³			
		RS = 152176 = 85			
(2)		Labour for cutting			
		62mm to 75mm dia			
		bamboo piles d/c			
		At 4 vide Tmp (p) 7			
		429.50 m @ 45.84/m			
		RS = 19421 = 71			
(3)		Labour for 2-1-7			
		8 Piling 75mm dia			
		bamboo sponner			
		d/c			
		At 4 vide Tmp (p) 7			
		231.00 m @ 5.31/m			
		RS = 1226.61			
(4)		Supplying &			
		piling of bamboo			
		at site d/c			
		At 4 vide Tmp (p) 7			
		101.00 m @ 188.37/m			
		RS = 20534 = 51			

Continuation

RS = 1,93,379 = 68

R. S. R. = 193 377-68

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(15)	Labour filling				
	empty cement				
	bags with local				
	Sand do do				
	Q. of vid. 7128/108				
	11656.0000 @ 37.05/100				
				RS = 431854-80	
				total RS = 6,25,234 = 48	
	add 12% G.S.T @ RS = 75028 = 13				
	add 1% Labour (OSPR) = 6252 = 34				
	seigniorage fees @ 10% bank			9326.63	
				total RS = 7,15,841 = 58	

Say RS = 7,15,842 = 00

23-11-2021
 23-11-2021
 23-11-2021

23-11-2021
 23-11-2021
 23-11-2021

Continuation