

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
Name of work - Restoration					
Work of flood damage					
part of Naranges to					
Malaha tola Road.					
Authority - E.E.R.W.D (W) Div - Sitamarhi					
Block - Parihar.					
1) providing and laying					
brick bats filling the					
ditch in road - all					
comp.					

Ditch vide p.no. (1) T.M.B.					
84.46 M ³					
16.89 M ³ M ³ @ 182 T = 25/M					
61.63 M ³ R					112613 = 0
(2) providing quarry materials					
Rabbish for filling the voids					
of brick bats - etc.					
Ditch vide p.no. (1) T.M.B.					
16.89 M ³ @ 873 = 01/M					R 14745 = 0
R. P. Singh, L. Singh, H. P. C. N. P. Singh					
@ 5 M. C. R. 3395/M					R 16975 = 0
Add 1% Labour Cost + R					0.00
Add 12% G.S.T					+ R 0.00
Add 10% Seigniorage fee + R					0.00
Total					144333 = 0
Signature					144331 = 0
Date 26/04/22					S.E.

Continuation

26/04/22
AC