

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, डुमराँव ।

पत्रांक 836

डुमराँव, दिनांक 04/8/2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, डुमराँव ।

सेवा में,

नोडल पदाधिकारी,
3054(MR)
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय:- शीर्ष MR New Maintenance Policy 2018 योजना अन्तर्गत 5(पाँच) वर्षीय अनुरक्षण का
आवंटन उपलब्ध कराने के संबंध में ।


महाशय,

उपर्युक्त विषयक के संबंध में कहना है कि शीर्ष MR New Maintenance Policy 2018
योजना अन्तर्गत 5(पाँच) वर्षीय अनुरक्षण के पथों का पथवार मांगी जाने वाली आवंटन की सूची पत्र के
साथ भवदीय के अवलोकनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित की जा रही है ।


सूचनार्थ सादर समर्पित ।

अनु०- यथोक्त

विश्वासभाजन



कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, डुमराँव ।



STANDARD FORMAT FOR ROADS QUARTERLY STATEMENT

PIU Name :- RWD, Works Division, **Dumroan**

1	Name of the Road	Basudeva to Chaugain via Keshath		
2	Batch No.	RM/BU/DUM/19/0005		
3	Project ID	10402008039		
4	Total Lenth of Road (in KM)	10.500		
5	Length of Road to Meet Required Service Level [Completed length](in Km) [1]	10.500		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount for Maintenance] (in Lakh)	92.97417		
8	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	4.64871		
Compliance Criteria	Standard Job Description	Non-Compliance		Reduction Payment [6]=[3]/[1]*[2]*[4]
		Length Non-Compliant [3]	Weighted Value for Payment Reduction (%) [4]	
I	PAVED ROADS (CARRIAGEWAY)	0	60%	0.00
II	SHOULDERS AND EMBANMENTS	0	10%	0.00
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	0	15%	0.00
IV	SIGNAGE AND ROAD SAFETY	0	10%	0.00
V	VEGATION	0	5%	0.00
TOTAL PAYMENT REDUCTION FOR THE QUARTER (IN Lakh) [5]				0.00000
TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]				4.64871

Date of inspection by E/I or his agent
Prepare by Contractor's self Control unit

Name and Designation of person inspecting road

Date

Signature of person inspecting road

(Signature)

Certify by E/I [signature] Date
Executive Engineer
Rural Works Department
Works Division, Dumroan

Executive Engineer
R. W. D. (W) Division
Dumroan

Government Of Bihar

OM01

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

To:-

Executive Engineer
RWD, Works Division Dumraon

Date:-

Road From:-Basudeva to Chaugain via Keshath
Length of Road :- 10.50 KM
Inspector :-

Position :-


No	standard Of Work Item Name	Work Unit	Unit Of Required in each Kilometer																
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	Comments
OMI100	Sealed payment																		
OMI101	Pothole Patching	m ²	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	No pothole found
OMI102	Surface Depression and Rut patching	m ³	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	No Surface Depression and Rut patching found
OMI103	Crad Sealings	Lm	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	No crack
	Surface Treatment		NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Not required
OMI104	(a) Loss of Aggregate (Surface Raveling)	m ²	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	No Loss of Aggregate (Surface raveling) found
	(b) Bleeding / Flushing	m ²	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	No bleeding / flushing found
OMI105	© Crocodile Cracking	m ²	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	No Crocodile cracking found
OMI106	Edge Repair	m ²	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Notified & repaired
OMI107	Digouts	m ²	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	
	Concrete pavement	m ³	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	
	Other activities																		
OM200	Shoulder																		
	Unsealed Shoulder																		
	(a) Edge Drop-off	Lm	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	No Edge Drop off found
OM201	(b) Roughness, Scouring or Potholes	Lm	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	No Roughness, Scouring or Potholes found
	(c) Holding water	Lm	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	No Holding Water Found
OM202	Embankment Repair	M ³	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Notified & repaired
	Other activities (Rain Cuts)	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	
OM300	Drainage including culverts major																		
OM301	Surface Drains & Verges	Lm	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	NA
OM302	Culvert Cleaning	No	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	DONE
OM303	Culvert and pit Repair	M ³	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	DONE
	Other activities (Willow washing)	M ²	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	NIL	Not required

No	standard Of Work Item Name	Work Unit	Unit Of Required in each Kilometer										Comments
			1	2	3	4	5	6	7	8	9	10	
OM400	Vegetation												
	Grass Control												Done
OM401	(a) Roadside- General Tidy	Ha	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Done
	(b) Clear near Safety signs, kilometer posts and roadside	Ha	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Done
	Tree and Shrub Management	No	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Done
OM402	Cutting Of Branches Of Trees	No	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Done
	Cutting Of Shrubs From Road Way	No	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Done
	Other activities (Trimming of Grass)	M ²	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Done
OM500	Safety Signage and Road												Not Required
OM501	Signs Maintenance	No	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Not Required
OM502	Guard Stones	Lm	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	N.A.
OM503	Distance Stones	No	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	N.A.
OM504	Road Marking	M ²	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Not Required
	Other activities												

Hand: 18/8/2021
for Maintenance

Hand: 18/8/2021
for Maintenance

Signature of Engineer
Rural Works Department
W.R. Division, Durness
Durness



In the
 18/8/21
 27963
 M. J. P. D.
 18/8/2021
 TE: Navanagar

btl
 28.07.2020
 AE Navanagar

10/08/2022
 EE
 Executive Engineer
 R.W.D. (W) Division
 Durgam

Name of Road :- VASUDEWA TO CHOUNGAI VIA KESATH . (MACHINE - BUXAR)

Date	Time	Section	Length	Bumps	Speed	OR	IRI	GATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	Road			
18/8/21	11:34:10	6	0.1	290	0	2900	2975	G	25.428018	84.191178	Normal
18/8/21	11:34:30	6	0.1	320	30.3	3200	3250	G	25.427838	84.192172	Normal
18/8/21	11:34:52	6	0.1	330	30.3	3300	3390	G	25.427643	84.193182	Normal
18/8/21	11:35:10	6	0.1	290	30.3	2900	2960	G	25.42753	84.194123	Normal
18/8/21	11:35:45	6	0.1	290	30.3	2900	2975	G	25.42772	84.19515	Normal
18/8/21	11:36:0	6	0.1	310	30.3	3100	3175	G	25.42772	84.196127	Normal
18/8/21	11:36:18	6	0.1	310	32.5	3100	3125	G	25.42762	84.19712	Normal
18/8/21	11:36:40	6	0.1	320	32.5	3200	3285	G	25.427518	84.198113	Normal
18/8/21	11:36:56	6	0.1	290	30.5	2900	2955	G	25.427337	84.19914	Normal
18/8/21	11:37:7	6	0.1	300	33.2	3000	3064	G	25.42723	84.20008	Normal
18/8/21	11:37:27	6	0.1	310	30.3	3100	3181	G	25.427142	84.201127	Normal
18/8/21	11:37:47	6	0.1	300	30.2	3000	3069	G	25.42722	84.202172	Normal
18/8/21	11:38:0	6	0.1	320	30.3	3200	3265	G	25.427415	84.203097	Normal
18/8/21	11:38:18	6	0.1	330	30.3	3300	3375	G	25.42741	84.204057	Normal
18/8/21	11:38:36	6	0.1	280	30.3	2800	2880	G	25.427228	84.20505	Normal
18/8/21	11:38:58	6	0.1	290	32.5	2900	2975	G	25.426922	84.205975	Normal
18/8/21	11:39:15	6	0.1	330	33.5	3300	3364	G	25.42678	84.206985	Normal
18/8/21	11:39:34	6	0.1	310	30.3	3100	3167	G	25.427	84.207978	Normal
18/8/21	11:39:52	6	0.1	340	30.2	3400	3462	G	25.427062	84.208838	Curve
18/8/21	11:40:5	6	0.1	350	32.5	3500	3561	G	25.42727	84.209697	Normal

Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY Road	Latitude	Longitude	Event
		No.									
18/8/21	11:40:30	6	0.1	320	33.2	3200	3265	G	25.427088	84.210638	Normal
18/8/21	11:40:48	6	0.1	330	30.3	3300	3364	G	25.4269	84.21173	Speed Breaker
18/8/21	11:40:58	6	0.1	290	32.5	2900	2975	G	25.426737	84.212677	Speed Breaker
18/8/21	11:41:16	6	0.1	300	30.3	3000	3062	G	25.426662	84.213687	Normal
18/8/21	11:41:36	6	0.1	280	30.2	2800	2872	G	25.426637	84.214662	Normal
18/8/21	11:41:51	6	0.1	310	32.5	3100	3172	G	25.426572	84.215622	Normal
18/8/21	11:42:9	6	0.1	330	30.2	3300	3380	G	25.426395	84.21668	Normal
18/8/21	11:42:25	6	0.1	310	30.5	3100	3180	G	25.426142	84.217625	Normal
18/8/21	11:42:42	6	0.1	320	32.5	3200	3265	G	25.42584	84.218518	Normal
18/8/21	11:42:56	6	0.1	330	32.5	3300	3364	G	25.425525	84.219512	Normal
18/8/21	11:43:16	6	0.1	340	30.2	3400	3462	G	25.425243	84.220538	Normal
18/8/21	11:43:29	6	0.1	310	30.3	3100	3182	G	25.42502	84.22143	Normal
18/8/21	11:43:47	6	0.1	300	32.5	3000	3080	G	25.424777	84.222423	Normal
18/8/21	11:43:56	6	0.1	280	30.2	2800	2880	G	25.4246	84.22343	Normal
18/8/21	11:44:12	6	0.1	290	32.5	2900	2960	G	25.424477	84.224377	Normal
18/8/21	11:44:28	6	0.1	300	30.2	3000	3072	G	25.42434	84.22542	Normal
18/8/21	11:44:47	6	0.1	280	32.5	2800	2872	G	25.424165	84.22643	Normal
18/8/21	11:44:59	6	0.1	330	30.2	3300	3364	G	25.42393	84.22739	Normal
18/8/21	11:45:12	6	0.1	310	32.5	3100	3175	G	25.423708	84.228315	Normal
18/8/21	11:45:30	6	0.1	290	30.2	2900	2970	G	25.423477	84.229308	Normal
18/8/21	11:45:42	6	0.1	290	30.3	2900	2970	G	25.423338	84.230218	Normal
18/8/21	11:45:57	6	0.1	310	31.5	3100	3175	G	25.423207	84.231278	Normal
18/8/21	11:46:12	6	0.1	320	32.5	3200	3255	G	25.423092	84.232238	Normal
18/8/21	11:46:37	6	0.1	320	30.5	3200	3265	G	25.422952	84.23	Normal
18/8/21	11:46:57	6	0.1	330	32.5	3300	3364	G	25.422838	84.234325	Normal
18/8/21	11:47:10	6	0.1	290	30.2	2900	2970	G	25.422672	84.235302	Normal
18/8/21	11:47:23	6	0.1	360	32.5	3600	3659	G	25.422593	84.236397	Normal
18/8/21	11:47:43	6	0.1	350	30.5	3500	3561	G	25.423332	84.236548	Normal
18/8/21	11:48:0	6	0.1	340	32.5	3400	3462	G	25.42422	84.236565	Normal

Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY Road	Latitude	Longitude	Event
		No.									
18/8/21	11:48:15	6	0.1	310	30.3	3100	3175	G	25.425107	84.236582	Normal
18/8/21	11:48:28	6	0.1	300	32.5	3000	3069	G	25.425972	84.23648	Normal
18/8/21	11:48:43	6	0.1	320	30.3	3200	3265	G	25.426958	84.236347	Speed Breaker
18/8/21	11:49:3	6	0.1	340	31.5	3400	3462	G	25.427923	84.236212	Speed Breaker
18/8/21	11:49:20	6	0.1	350	32.5	3500	3561	G	25.42865	84.23606	Normal
18/8/21	11:49:39	6	0.1	290	30.2	2900	2980	G	25.429558	84.235858	Normal
18/8/21	11:49:54	6	0.1	320	32.5	3200	3280	G	25.430428	84.235707	Normal
18/8/21	11:50:9	6	0.1	330	30.5	3300	3355	G	25.431295	84.235522	Normal
18/8/21	11:50:24	6	0.1	310	30.3	3100	3173	G	25.432652	84.2351	Normal
18/8/21	11:50:44	6	0.1	340	30.3	3400	3462	G	25.433787	84.234982	Culvert
18/8/21	11:50:58	6	0.1	350	30.3	3500	3561	G	25.434592	84.235437	Normal
18/8/21	11:51:17	6	0.1	330	32.5	3300	3364	G	25.435318	84.236127	Normal
18/8/21	11:51:39	6	0.1	300	30.2	3000	3069	G	25.43612	84.236178	Normal
18/8/21	11:51:57	6	0.1	310	30.3	3100	3177	G	25.437013	84.236077	Normal
18/8/21	11:52:9	6	0.1	280	31.5	2800	2872	G	25.43792	84.235925	Normal
18/8/21	11:52:22	6	0.1	270	30.3	2700	2773	G	25.438775	84.23579	Normal
18/8/21	11:52:40	6	0.1	300	30.2	3000	3069	G	25.439702	84.23569	Normal
18/8/21	11:52:58	6	0.1	310	30.3	3100	3167	G	25.440563	84.235622	Normal
18/8/21	11:53:16	6	0.1	320	32.5	3200	3265	G	25.44142	84.235622	Normal
18/8/21	11:53:33	6	0.1	320	33.2	3200	3265	G	25.442423	84.23579	Normal
18/8/21	11:53:50	6	0.1	280	32.5	2800	2877	G	25.443295	84.235892	Normal
18/8/21	11:54:8	6	0.1	330	30.2	3300	3364	G	25.444142	84.235975	Normal
18/8/21	11:54:18	6	0.1	340	32.5	3400	3462	G	25.445182	84.236077	Normal
18/8/21	11:54:34	6	0.1	290	30.2	2900	2970	G	25.44602	84.236178	Normal
18/8/21	11:54:50	6	0.1	280	30.2	2800	2872	G	25.446963	84.236278	Normal
18/8/21	11:55:5	6	0.1	280	30.2	2800	2880	G	25.447865	84.236363	Normal
18/8/21	11:55:22	6	0.1	310	32.5	3100	3180	G	25.448713	84.236447	Normal
18/8/21	11:55:36	6	0.1	290	30.2	2900	2970	G	25.449612	84.236548	Normal
18/8/21	11:55:52	6	0.1	330	30.3	3300	3364	G	25.450528	84.236615	Normal
18/8/21	11:56:0	6	0.1	340	32.5	3400	3462	G	25.451522	84.2367	Speed Breaker
18/8/21	11:56:30	6	0.1	310	30.2	3100	3167	G	25.4523	84.236868	Normal
18/8/21	11:56:58	6	0.1	300	32.5	3000	3069	G	25.453307	84.236918	Normal
18/8/21	11:57:16	6	0.1	310	30.3	3100	3180	G	25.454092	84.236902	Normal

Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY Road	Latitude	Longitude	Event
		No.									
18/8/21	11:56:46	6	0.1	320	30.2	3200	3250	G	25.455037	84.236885	Normal
18/8/21	11:57:4	6	0.1	290	32.5	2900	2970	G	25.455988	84.236902	Normal
18/8/21	11:57:34	6	0.1	270	30.2	2700	2773	G	25.456848	84.236968	Normal
18/8/21	11:57:59	6	0.1	340	32.5	3400	3480	G	25.457787	84.237188	Normal
18/8/21	11:58:28	6	0.1	310	30.5	3100	3150	G	25.458652	84.237322	Normal
18/8/21	11:58:56	6	0.1	330	33.2	3300	3364	G	25.459552	84.23744	Normal
18/8/21	11:59:26	6	0.1	340	32.5	3400	3462	G	25.460475	84.237575	Normal
18/8/21	11:59:57	6	0.1	310	30.2	3100	3167	G	25.461328	84.237677	Normal
18/8/21	12:0:24	6	0.1	280	32.5	2800	2872	G	25.462173	84.237777	Normal
18/8/21	12:0:49	6	0.1	310	30.2	3100	3167	G	25.46306	84.237878	Normal
18/8/21	12:1:6	6	0.1	350	32.5	3500	3561	G	25.464023	84.238013	Normal
18/8/21	12:1:34	6	0.1	280	30.2	2800	2860	G	25.46489	84.23813	Normal
18/8/21	12:1:57	6	0.1	320	32.5	3200	3265	G	25.46587	84.238248	Normal
18/8/21	12:2:19	6	0.1	310	30.2	3100	3178	G	25.466725	84.238	Normal
18/8/21	12:2:44	6	0.1	280	32.5	2800	2877	G	25.467687	84.23847	Normal
18/8/21	12:3:4	6	0.1	290	30.2	2900	2975	G	25.468477	84.238602	Normal
18/8/21	12:3:31	6	0.1	280	30.3	2800	2872	G	25.469375	84.23872	Normal
18/8/21	12:3:54	6	0.1	270	30.3	2700	2773	G	25.470202	84.23872	Normal
18/8/21	12:4:19	6	0.1	320	30.3	3200	3277	G	25.471158	84.238703	Normal
18/8/21	12:4:44	6	0.1	280	30.3	2800	2872	G	25.472088	84.23845	Normal
18/8/21	12:4:59	6	0.1	290	32.5	2900	2970	G	25.472918	84.238332	Normal
18/8/21	12:5:24	6	0.1	270	32.5	2700	2773	G	25.473742	84.23847	Normal
18/8/21	12:5:51	6	0.1	300	30.2	3000	3080	G	25.474678	84.238635	Normal